

Avaya Solution & Interoperability Test Lab

# Application Notes for the Verint ULTRA 9.3 using Service Observation with Avaya Communication Manager 3.0 - Issue 1.0

#### Abstract

These Application Notes describe the configuration steps required for the Verint ULTRA 9.3 to successfully interoperate with Avaya Communication Manager 3.0. Functionality and failover tests were validated and performance testing was conducted in order to verify operation under load.

Verint ULTRA 9.3 is a call recording solution capable of capturing audio from Avaya Communication Manager 3.0 using a variety of integration mechanisms. ULTRA uses Avaya Telephony Service API (TSAPI) to extract call event information and the Device and Media Control API (also known as Communication Manager API) of Avaya Application Enablement Services (AES) to obtain the audio. The test configuration consisted of an Avaya S8500 Media Server with an Avaya G650 Media Gateway running Avaya Communication Manager 3.0, and an Avaya AES Server.

Information in these Application Notes has been obtained through interoperability compliance testing and additional technical discussions. Testing was conducted via the Developer*Connection* Program at the Avaya Solution and Interoperability Test Lab.

### 1. Introduction

These Application Notes describe a compliance-tested configuration utilizing Avaya Communication Manager 3.0 and Verint ULTRA 9.3 recording solution. ULTRA used Avaya Telephony Service API (TSAPI) to extract call event information and the Device and Media Control API (also known as Communication Manager API) of Avaya Application Enablement Services (AES) to obtain the audio.

Communication Manager API stations are administered as virtual stations, or softphones, in Avaya Communication Manager and are used by ULTRA as recording ports. When a monitored telephone is on an active call, ULTRA uses a Communication Manager API station to service observe the monitored telephone and capture the audio from the call. Since softphones require IP connectivity, C-LAN and MEDPRO boards are required in the Avaya Media Gateway to support signaling and RTP audio streaming, respectively.

The ULTRA recording application includes three software components:

The CMAPI Manager interfaces between the CMAPI Controller and the Media Handler components.

The CMAPI Controller is responsible for communicating with the CMAPI Connector (AES server).

The Media Handler designates ports for receiving audio, and handles the audio that it receives.

All three components are installed on the VoIP Acquisition Module.



Figure 1: Avaya Communication Manager, Avaya Application Enablement Services Server and Verint ULTRA Compliance Test Configuration

HJP; Reviewed: SPOC 10/28/2005 Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved. 2 of 28 Verint-ACM-SO.doc

### 2. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided:

Equipment	Software
Avaya S8500 Media Server with Avaya G650	Avaya Communication
Media Gateway	Manager 3.0 (340.3)
Avaya 4620 IP Telephones	1.9.1
Avaya C364T-PWR Converged Stackable	4.3.12
Switch	
Application Enablement Services Server	3.0
Verint ULTRA	9.3

### 3. Configure Avaya Application Enablement Services Server

Log into the Avaya Application Enablement Services (AES) Server OAM pages. The Avaya AES server summary page indicates the number of available licenses; ensure that the relevant licenses are installed.



Ensure that all the services are running under the Maintenance  $\rightarrow$  Service Controller option. At a minimum, the CMAPI, TSAPI and Transport Layer services should be running.

AVAYA	OAM	
OAM Home CTI OAM Home Administration Status and Control Maintenance Service Controller Backup Database Restore Database Import SDB Logs Utilities Help Logout	You are here: > <u>Maintenance</u> Service Controller Service Co ASAI Link Manager CMAPI Service CVLAN Service DLG Service Transport Layer Service TSAPI Service For status on actual services, pla	<ul> <li>Service Controller</li> <li>ntroller Status</li> <li>Running</li> <li>Running</li> <li>Running</li> <li>Running</li> <li>Running</li> <li>Running</li> <li>Running</li> <li>Running</li> </ul>
	Start Stop Restart Service	Restart AE Server Restart Linux

Add a switch connection name by clicking on Switch Connections under Administration. A password of at least 12 alphanumeric characters needs to be entered; this is the exact password that will be used when configuring Avaya Communication Manager.

AVAYA	OAM	
OAM Home CTI OAM Home Administration Local IP	You are here: > <u>Administration</u> > <u>Swi</u> Switch Connections	tch Connections
Ports Switch Connections CTI Link Admin CMAPI Configuration TSAPI Configuration	Connection Name	Add Connection Number of Active Connections 1
<u>Security Database</u> <u>Status and Control</u> <u>Maintenance</u> Logs	Edit Connection Edit CLAN IPs	Edit H.323 Gatekeeper

Click on Edit CLAN IPs in the Switch Connections page. Enter the IP address of a C-LAN and then click on Add Name or IP.

AVAYA	OAM	
OAM Home CTI OAM Home ✓ Administration Local IP	You are here: > Administration > Edit CLAN IPs - 8500	Switch Connections
Ports Switch Connections CTI Link Admin CMAPI Configuration TSAPI Configuration Security Database Status and Control Maintenance Logs	Name or IP Address          Image: Name or IP Address         Image: Imag	Add Name or IP Status In Use

Return to the Switch Connections page, select the Switch Connection configured above, and click on Edit H.323 Gatekeeper. Enter the IP address of a C-LAN and then click on Add Name or IP.

AVAYA	OAM
OAM Home	
CTI OAM Home	You are here: > <u>Administration</u> > <u>Switch Connections</u>
🗕 Administration	L Edit II 222 Catakaanan 8500
Local IP	Tealt H.323 Gatekeeper - 8500
Ports	
Switch Connections	Add Name or IP
<u>CTI Link Admin</u>	Name or IP Address
<u>CMAPI Configuration</u>	10.10.12
TSAPI Configuration	
Security Database	
<ul> <li><u>Status and Control</u></li> </ul>	
▶ <u>Maintenance</u>	
▶ <u>Logs</u>	

Click on Administration  $\rightarrow$  CTI Link Admin  $\rightarrow$  TSAPI Links. Click on Add Link and enter the Link, Switch Connection, Switch CTI Link Number (must match CTI link number configured on the Avaya Communication Manager in Section 4.1). Click on Apply Changes.

Αναγα	OAM
OAM Home CTI OAM Home Administration Local IP Ports Switch Connections CTI Link Admin TSAPI Links CVLAN Links DLG Links CMAPI Configuration TSAPI Configuration Security Database Status and Control Maintenance Logs Help	You are here: > Administration > CTI Link Admin > TSAPI Links         Add / Edit TSAPI Links         Link:       3         Switch Connection:       8500 •         Switch CTI Link Number:       3 •         Apply Changes       Cancel Changes
<u>Logout</u>	© 2005 Avaya Inc. All Rights Reserved.

AVAYA	<u>OAM</u>			
OAM Home	U			
CTI OAM Home	You are here:	> <u>Administration</u> >	<u>CTI Link Admin</u> >	TSAPI Links
<u>     Administration    </u>				
Local IP	📑 TSAPI	Links		
Ports				
Switch Connections	Link	Switch Connection	Switch CTI Link	ASAI Link
👻 CTI Link Admin	LINK	Switch Connection	#	Version
TSAPI Links	و 🕥	8500	3	4
CVLAN Links	Add Link	Edit Link Delete Link		
DLG Links				
<u>CMAPI Configuration</u>				
TSAPI Configuration				
Security Database				
Status and Control				
Maintenance				

During compliance testing, the TSAPI Security Database (SDB) was not used for testing convenience. The relevant configuration screen is shown below.



Note: In environments where the TSAPI SDB is enabled, the devices to be monitored must be configured in the TSAPI SDB.

A User Id and password needs to be configured for the Verint ULTRA server to communicate as a TSAPI Client with the AES server. Click on OAM Home  $\rightarrow$  User Management and log into the User Management pages. Click on User Management and then Add User. The CT User field needs to be set to "Yes".

AVAYA	OAM		
OAM Home			
User Management Home	You are here: > <u>Use</u>	<u>r Management</u> > <u>Add Use</u>	r
✓ <u>User Management</u> List All Users	🚦 Add User		
<u>Add User</u> <u>Search Users</u>	Fields marked with * ca	an not be empty.	
Modify Default User	* User Id	hparekh	
<ul> <li><u>Change User Password</u></li> <li><u>Service Management</u></li> </ul>	* Common Name	heman	
▶ <u>Help</u>	* Surname	parekh	
Logout	New Password		
	Confirm New Password		
	Admin Note		
	Avaya Role	None	
	Business Category		
	Car License		
	CM Home		
	Css Home		
	CT User	Yes 💌	

Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved.

# 4. Configure Avaya Communication Manager

Different features of Avaya Communication Manager need to be configured for the recording modes to be tested. Refer to the Administration Guide for Avaya Communication Manager for further details – Avaya Document 555-233-506 [1]. The specific options are detailed below.

#### 4.1. Configure the CTI Link

Regardless of the mode of audio recording, a CTI link is required to provide call details for each recording. ULTRA supports a TSAPI link to Avaya Communication Manager.

Although both ASAI Link Core and Plus Capabilities were enabled in Avaya Communication Manager, only the Core Capabilities are required by the ULTRA solution.

display system-parameters customer-opti	Page 3 of 11		
OPTIONA	λL	FEATURES	
Abbreviated Dialing Enhanced List?	n	Audible Message Waiting? :	n
Access Security Gateway (ASG)?	n	Authorization Codes?	n
Analog Trunk Incoming Call ID?	n	Backup Cluster Automatic Takeover? :	n
A/D Grp/Sys List Dialing Start at 01?	n	CAS Branch?	n
Answer Supervision by Call Classifier?	n	CAS Main?	n
ARS?	У	Change COR by FAC?	n
ARS/AAR Partitioning?	У	Computer Telephony Adjunct Links? :	n
ARS/AAR Dialing without FAC?	У	Cvg Of Calls Redirected Off-net?	n
ASAI Link Core Capabilities?	У	DCS (Basic)?	n
ASAI Link Plus Capabilities?	У	DCS Call Coverage?	n
Async. Transfer Mode (ATM) PNC?	n	DCS with Rerouting?	n
Async. Transfer Mode (ATM) Trunking?	n		
ATM WAN Spare Processor?	n	Digital Loss Plan Modification? :	n
ATMS?	n	DS1 MSP? :	n
Attendant Vectoring?	n	DS1 Echo Cancellation?	n
(NOTE: You must logoff & login	tc	effect the permission changes.)	

A CTI Link needs to be configured to provide the logical connection between Avaya Communication Manager and the ULTRA Server. The type must be set to "ADJ-IP". The extension number must be valid in the dial plan of Avaya Communication Manager.

```
display cti-link 3 Page 1 of 2

CTI LINK
CTI Link: 3
Extension: 13000
Type: ADJ-IP
COR: 1
Name: TSAPI link 3
```

The Node-Names form must be modified to include the IP addresses of the C-LAN board and the Avaya Application Enablement Services Server, as shown below:

display node-names	ip		Page 1 of 1
		IP NODE NAMES	
Name	IP Ad	ddress Name	IP Address
AEServer	10 .10	.10 .20	
CDR_Server	10 .10	.30 .20	
G350	10 .10	.30 .10	
VAL	10 .10	.10 .14	
clan	10 .10	.10 .12	
default	0.0	.0 .0	
medpro	10 .10	.10 .13	
procr	10 .10	.10 .10	
	•		
	•		
(8 of 8 adminis	stered no	ode-names were displayed )	
Use 'list node-name	es' comma	and to see all the administere	ed node-names
Use 'change node-na	ames ip :	xxx' to change a node-name 'xx	xx' or add a node-name

The IP Services form needs to be configured to define a link to the Avaya Application Enablement Services server as shown below.

display ip	-services						Page	1 0	of	4
			IP	SERVICE	ES					
Service	Enabled	Local		Local		Remote	R	emote		
Туре		Node		Port		Node	P	ort		
SAT	У	clan		5023	any		0			
AESVCS	У	clan		8765						
CDR1		clan		0	CDR.	_Server	9	000		

On the AE Services Administration page of the ip-services form, enter the hostname of the AES server and the password (which must match the password configured on the AES in Section 3), set Enabled to "y".

change ip-ser	vices			Page 4 of	4
		AE Services Administra	ation		
Server ID	AE Services Server	Password	Enabled	Status	
1:	AEServer	aeserver123456	У	in use	
2:					
3:					

#### 4.2. Configure Service Observation

Avaya Communication Manager must be configured to allow monitoring devices to Service Observe and to allow monitored devices to be Service Observable. These permissions are configured by Class of Restriction (COR). COR 1 was assigned to both types of devices. The configuration for COR 1 is shown in the following screen.

```
change cor 1
                                                                   4
                                                     Page
                                                           1 of
                             CLASS OF RESTRICTION
               COR Number: 1
          COR Description: Main COR
                     FRL: 0
                                                           APLT? y
 Can Be Service Observed? y
                                      Calling Party Restriction: none
Can Be A Service Observer? y
                                       Called Party Restriction: none
Partitioned Group Number: 1
                                 Forced Entry of Account Codes? n
                                           Direct Agent Calling? n
        Priority Queuing? n
    Restriction Override: none
                                    Facility Access Trunk Test? n
    Restricted Call List? n
                                            Can Change Coverage? n
                                       Fully Restricted Service? n
           Access to MCT? y
Group II Category For MFC: 7
        Send ANI for MFE? n
           MF ANI Prefix:
                                       Automatic Charge Display? n
Hear System Music on Hold? y
                              PASTE (Display PBX Data on Phone)? n
                       Can Be Picked Up By Directed Call Pickup? n
                                    Can Use Directed Call Pickup? n
                                    Group Controlled Restriction: inactive
```

In addition, a Feature Access Code to perform Service Observation must be configured. The Service Observation access code must also be entered in the configuration of the Verint ULTRA Server (see Section 5.1). The appropriate page of the Feature Access Code configuration is shown below.

```
display feature-access-codes Page 5 of 6

FEATURE ACCESS CODE (FAC)

Service Observing Listen Only Access Code: *86

Service Observing Listen/Talk Access Code: *87

Remote Logout of Agent Access Code:

Enter 1-4 digit number; * and # may be used as first digit
```

If necessary and allowed in an environment, the Service Observing Warning Tone may be disabled from the feature-related system parameters form.

change system-parameters features	Page 11 of 16
FEATURE-RELATED SYSTEM	M PARAMETERS
CALL CENTER SYSTEM PARAMETERS EAS	
Direct Agent Announcement Extension:	: Delay:
VECTORING	
Converse First Data Delay:	: 0 Second Data Delay: 2
Converse Signaling Tone (msec):	: 100 Pause (msec): 70
Reverse Star/Pound Digit For Collect Step?	? n
SERVICE OBSERVING	
Service Observing: Warning Tone?	<b>? n</b> or Conference Tone? n
Service Observing Allowed with Exclusion?	? n

#### 4.3. Configure the Active Station-side Avaya Communication Manager API Station

Station-side monitoring is provided using the service observation feature and Avaya Communication Manager API stations. The Communication Manager API station is configured as an extension in Avaya Communication Manager with "IP Softphone" enabled so that an Avaya Communication Manager API application is able to take control of the device. ULTRA records the conversations of monitored telephones by bridging (using Service Observation) Communication Manager API stations onto calls that the monitored telephones are participating in. When a Communication Manager API station is bridged onto an active call, the RTP stream of the call is directed to the IP addresses of the Communication Manager API stations, which reside on the ULTRA server. An example configuration of a Communication Manager API station is shown below.

display station 14000			Page 1	of	4
	STA	<b>FION</b>			
Extension: 14000		Lock Messages?	n	BCC:	0
Type: 4620		Security Code:	12345	TN:	1
Port: S00000		Coverage Path 1:		COR:	1
Name: IP10000		Coverage Path 2:		COS:	1
		Hunt-to Station:			
STATION OPTIONS					
Loss Group:	19	Personalized Ring	ging Patter	n: 1	
		Messa	ige Lamp Ex	t: 140	000
Speakerphone:	2-way	Mute But	ton Enable	d?y	
Display Language:	english	Expan	sion Modul	e? n	
Survivable GK Node Name:					
Survivable COR:	internal	Media	Complex Ex	t:	
Survivable Trunk Dest?	У	I	P SoftPhon	e?y	
		IP Vide	eo Softphon	e? n	

ULTRA requires that the Communication Manager API station extensions be consecutive and all have the same security code (password).

# 5. Configure the Verint ULTRA Server

The following describes the installation and configuration of Verint ULTRA.

### 5.1. Configuring Station Side Recording

Configuration of Station side recording is achieved by running the ULTRA Configuration Wizard. To activate the Wizard, open the System Tools (a shortcut on the server desktop) and in the Run tab, double-click the Configuration Wizard link.



The Configuration Wizard is a web browser application that can be accessed from any connected machine, but the ULTRA server was used for convenience.

Note the following parameters in the Voice Acquisition page of the wizard:

- 1. Set Tapping Mode to "VoIP Delivery CMAPI".
- 2. Set CMapi Connector Server IP to the Avaya Application Enablement Services IP address.
- 3. Set Switch IP Address or DNS Name to the C-LAN IP address.
- 4. Set Virtual Extension Start From to the first Communication Manager API station extension (configured in Section 4.3).
- 5. Set the CMapi Login Password to the Communication Manager API station password.
- 6. Set the CMapi Silent Observe Code to the Avaya Communication Manager Service Observing Listen Only Access Code (see above Section 4.2).
- 7. The rest of the parameters should be left with the default values.

🖉 ULTRA Express Configuration Wiz	zard - Microsoft Internet Explorer	
<u>File E</u> dit <u>V</u> iew F <u>a</u> vorites <u>T</u> ools	Help	
↔ Back • → • 🙆 🙆 🚮 🔞	Search 🔝 Favorites 🎯 Media 🎯 🖏 - 🎒	
Address 🙆 http://localhost/UCW/		✓ Co Links »
	TRA EXPRESS	
Welcome	Recording Environment	×
🛃 Time Setup		
Voice Acquisition		
Application Setup	SNMP Manager (IP address of Divs Halle) SNMP Community Public	
🔁 Data Fields		
Backup	Tapping Mode IVOLP Delivery - CMAPI	
Apply Configuration	Number of Simultaneous Contacts 100	
	CMapi Connector Server IP 10.10.10.20	
	Switch IP Address or DNS Name 10.10.10.12	
	SoftPhone Preferred Codec G729	
	Virtual Extension Start From 14000	
	CMapi Login Password *****	
	Confirm Password	
	CMapi Silent Observe Code *86	
		< Previous Next >
C Done		🔠 Local intranet

The final step is to apply the configuration changes.

🚰 ULTRA Express Configuration Wize	ard - Microsoft Internet Explorer		X
<u>File Edit View Favorites T</u> ools	Help		
수 Back 🔹 🤿 🖉 🙆 🖓 🗔 S	iearch 🗽 Favorites 🎯 Media 🧭 🛃 🍎		
Address 🕘 http://localhost/UCW/			✓ (∂Go Links »
	TRA EXPRESS		
Welcome	Step 1: General System Configuration	Apply Configuration	
<ul> <li>Time Setup</li> <li>Voice Acquisition</li> </ul>			
Application Setup			
🔁 Data Fields	Step 2: IntelliLink Configuration	Run Utility	
<ul> <li>Backup</li> <li>Apply Configuration</li> </ul>	Step 3: VoIP Configuration	Run Utility	
Done			< Previous Finish

### 5.2. Configuring the CTI Link

Configuring the CTI link starts by running the IntelliLink Configuration Wizard (launched from the ULTRA tab in System Tools).

System Tools
Eile Group
Configuration General Run ULTRA
Application Manager
🖗 Daylight Saving Time Manager
IntelliLink Configuration
Canguage Setup
1 Management Tools
a Restore
🗳 ULTRA Online Help

ULTRA uses the generic switch name of "Avaya ECLIPS" to cover Avaya Communication Manager. Right-click and select the Avaya ECLIPS option, and click Next.



Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved. The following dialog box appears to select the API to communicate with Avaya Communication Manager. Select TSAPI and click on Next.



Since much of the major configuration options are not changeable after this stage has been reached, a warning dialogue box appears confirming the Switch Name and CTI Protocol have been correctly selected. Click OK.



From the ULTRA tab in System Tools, double-click on IntelliLink Configuration.

System Tools	_ 🗆 🗙
Eile Group	
Configuration General Run ULTRA	
Deplication Manager	
🖗 Daylight Saving Time Manager	
IntelliLink Configuration	
Tanguage Setup	
🖆 Management Tools	
Restore	
🗳 ULTRA Online Help	
	- 1
	- 1

Select the General tab, verify that the Trunk-side recording box is unchecked and click OK.

IntelliLink	General Advanced Simul	ator   WatchDog   IntelliLink /	API Web Service   Private Data	
	Trunk-side recording			
	Logout agents if IntelliLink is a	lisconnected for more than 10	minutes	
	Duplicate PBX IDs or Extension	15		
	PBX IDs are duplicate act	oss switches		
	Extensions are duplicate a	across switches		
			Save Changes	0

Click on IntelliLink  $\rightarrow$  Avaya ECLIPS  $\rightarrow$  TSAPI. In the General tab, configure the following:

- Server Name enter "AVAYA#<Switch Connection Name>#CSTA#<AES server hostname>. The Switch Connection Name should match the Switch Connection configured in Section 3.
- Login ID and Password enter the login information for the user created in Section 3.

IntelliLink Configuration Utilit	У			
IntelliLink IntelliLink IntelliContended TSAPI Devices Channel Mapping IntelliContended In	General Advanced Server Name Login ID Password	Private Data		
			Save Changes	OK

Click on IntelliLink  $\rightarrow$  Avaya ECLIPS  $\rightarrow$  Devices.

In the section labeled Extensions, enter the range of station extensions to be monitored by the CTI link. Note that this does NOT imply that these stations (devices) will be recorded – that is the subject of additional configuration and is based on recording mode. This configuration simply allows the CTI link to monitor these devices for activity.

□ IntelliLink Configuration Utility					_ 🗆 🗙
⊡… IntelliLink			(	_ ⊢Multiple Selectio	n Modification
🛱 😑 Avava ECLIPS (Switch1	#	Extension	Monitored		
TSAPI	1	10000	Yes	Monitored	<u> </u>
🛛 😑 Devices	2	10001	Yes		
🕒 😑 Channel Mapping	3	10002	Yes		
	4	10003	Yes		Delete
	5	10004	Yes	- Eutonaiana	
	6	10005	Yes	Extensions	
	7	10006	Yes		Append
	8	10007	Yes	From Extension	To Extension
	9	10008	Yes		
	10	10009	Yes	1	
	11	10010	Yes		
				J	Devices with IP
				File Uptions	
				C Append	Export Import
				File Name	
			<u>•</u>		
				0.01	
			_	pave changes	

Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved. ULTRA uses a technique called Channel Mapping to allow a recording channel to be associated with a monitored telephone. The mapping defined allows station 10000 to be recorded by channel 1 and station 10001 by channel 2, and so on.

DintelliLink Configuration Utility						×
IntelliLink Configuration Utility     IntelliLink     Avaya ECLIPS (Switch1	# 1 2 3 4 5 6 7 7 8 9 10 11 12 12 13	Module 101 101 101 101 101 101 101 101 101 10	Channel 1 2 3 4 4 5 6 7 7 8 9 9 10 10 11 11 2 13	Device 10000 10001 10002 10003 10004 10005 10006 10007 10008 10009 10010		Add/Modify Modules and Channels From module:  Map Channels Map module:  101 From channel:  From device:  Unmap Channels Select the channels to unmap and click Unmap. Unmap Delete Module Module: Delete
	15 16 17 18 10	101 101 101 101 101	15 16 17 18 10		-	File Options  File Name:  File Name: F
						Save Changes OK

The last step is to restart the IntelliLink and VAM services using the watchdog application (also can be found in the system tools).

Name	Туре	Status	<b></b>	Start
SP.NET Process Monitor	Service	Running		
lackupService	Service	Running		Stop
FM	Service	Running		
atabasesMonitorService	Service	Running		Chan All
nfolink	Service	Running		
ntelliConnect Service	Service	Running		
ntelliLink Databank	Service	Running		<u>S</u> tartup
ntelliLinkAPIWS	Service	Running		
1AS Service	Service	Running		
PurgerService	Service	Running		
INMP	Service	Running	<b>_</b>	
	- ·	<u> </u>		Close

Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved.

#### 5.3. Configuring Verint Server Network Cards

During compliance testing, ULTRA used a single Network Interface Card (NIC) for exchanging control messages with the AES server and for receiving RTP streams from MEDPRO boards. ULTRA may also be configured to use a dedicated NIC for receiving the RTP streams. To configure the dedicated NIC, double-click on VOIP Nic Manager under the Configuration tab in System Tools.



Select the dedicated NIC from the list and click on Set CMAPI.

🖷 VoIP NIC Manager		
NIC Description	LAN Connection Name	
Network Adapter	CMAPI NIC	
Network Adapter	ULTRA NIC	
		View Windows <u>N</u> etwork Connections
		Set CMAPI
Click to set up the selected NIC for CMapi This will rename the nic to CMAPI NIC .		

#### 5.4. Replaying the Voice Recordings

The IntelliPortal is a browser-based application allowing the actual recordings that have taken place to be both inspected for data and voice content. This utility was used throughout testing to validate successful recording of the various tested call scenarios.

🗿 ULTRA IntelliPortal -	Microso	oft Internet	Explorer								
Ele Edit Yew Favorites Iools Help											
🔾 Back - 🕤 - 🖹 🗟 🏠 🔎 Search 👷 Favorites 🤣 🎘 - 🌺 🚍 🖓											
Address 🗿 http://10.10.10.	.52/ultra/	gridplayback/Gr	idPlaybackIn	dex.asp×	?Update	DS=1&WorldName=etm&fo	idertype=PrivateFolder&fold	dername=newsearc	hSession	~	🔁 Go Links »
				Call .				τ			Help
Transaction	s <u>Ho</u>	me			4		641			Search	Preferences
Contacts: 1 - 47 Sor	rted Bv: S	tart Time								2	Save Search
			_	_	_			_	_		
Contacts	Dlav	Duration	Agent			Dialed From (ANI)	Dialed To (DNIS)	Extension	Data		
9/9/2005 1:07:25 2 PM	00	00:00:08	rigene		U	10000	10010	10000			
8/9/2005 1:07:30 1 PM	00	00:00:06				10000	10010	10000	0		
8/9/2005 12:26:32.0 PM	00	00:00:47				10000	10001	10010	ŏ		
8/9/2005 12:26:09.8 PM	00	00:00:58				10000	10001	10001	0		
8/9/2005 12:26:09 7 PM	00	00:01:09				10000	10001	10000	õ		
8/8/2005 8:23:00 5 PM	00	00:00:03				10000	10001	10010	ŏ		
8/8/2005 8:22:44.0 PM	00	00:00:21				10000	10001	10001	ŏ		
8/8/2005 8:22:43.9 PM	00	00:00:21				10000	10001	10000	õ		
8/8/2005 7:56:58.5 PM	00	00:00:15				10000	10001	10010	õ		
8/8/2005 7:56:38.6 PM	00	00:00:45				10000	10001	10001	õ		
8/8/2005 7:56:38.5 PM	00	00:00:45				10000	10001	10000	õ		
8/8/2005 7:50:17.8 PM	00	00:00:16				10000	10001	10010	õ		
8/8/2005 7:49:52.7 PM	00	00:00:52				10000	10001	10001	õ		
8/8/2005 7:37:39.5 PM	00	00:00:26				10000	10001	10010	0		
8/8/2005 7:37:21.3 PM	00	00:00:44				10000	10001	10001	0		
8/8/2005 7:34:13.8 PM	00	00:00:22				10000	10001	10010	0		
8/8/2005 7:33:53.7 PM	00	00:00:42				10000	10001	10001	0		
8/8/2005 7:03:59.8 PM	00	00:00:12				10000	10001	10010	0		
8/8/2005 7:03:46.5 PM	00	00:00:17				10000	10001	10001	0		
0.10.1000E 2.00.E1 2.0M	00	00.00.07				10000	10001	10010	0	*	
🕘 Done										🥑 Inte	met

A dedicated workspace page provides the ability to see a whole call with its different segments (sessions).

🚰 ULTRA IntelliPortal - Microsoft Internet Exp	olorer			X		
Ele Edit View Favorites Iools Help						
J= Back + → → (2) (2) (2) (2) (2) Favorites (2) Media (2) (3) + (4)						
Address Addres	i i i i i i i i i i i i i i i i i i i	- 18 Maalal Jama - atao 8 fa lalaataa	- Did interfalide 2 falide reason - names and fa	wine Co Links X		
Mgaress Territraturaturaturaturaturaturaturaturaturat	unaybackundex.aspx?opuacet	55=18WorldName=ethildiolderty	pe=Privater-older oldern ante=newsearch se			
Transactions Home   Back	to list		VERINT	Help Search Preferences		
Download Send Customer Xperie	nce Flags					
Contact (8:22:43 PM) Segment 1 -	Segment Informa	ition	Contact Information	on 🔺		
Segment 1/3 - (Start 8:22:43 PM)	Site Name		Contact Analysis	False		
PBX ID:	Acquisition Module	101	Exception	CC2252255 401		
	Channel	1	Contact ID Number of Holds	662353256401		
	Start Time	8/8/2005 8/22/43 PM	Number of Transfers Total Hold Time Start Time			
	ned miner	8/8/2005 8:23:05 PM 0				
	Screen Acquisition			8/8/2005		
			Start Hills	8:22:43 PM		
	Dialed From (ANI)	10000				
	Dialed To (DNIS)	10001				
	Switch Call ID	1422				
A MI MI A DA MA A MI MA A MA A MA A MA A	Extension	10000				
	PBX ID					
TERMAN AN ANALY POLICE	Duration	00:00:21				
00:00 / 00:21	Remark By					
	Remark On			•		
Damanic Dur						
Kemark By:						
On: Save						
😸 Done				🔹 🚺 🔮 Internet		

Solution & Interoperability Test Lab Application Notes ©2005 Avaya Inc. All Rights Reserved.

# 6. Interoperability Compliance Testing

A generic voice recording test plan was used and customized to include the specific features of the Verint ULTRA 9.3.

The interoperability compliance test included functionality and performance load testing. The testing examined the Verint ULTRA 9.3 interoperability with Avaya Communication Manager 3.0. The majority of the testing focused on the ability of the Verint ULTRA application to record calls originated and terminated by monitored telephones and replay the voice recordings correctly. The source and destination of each call recording was verified.

### 6.1. General Test Approach

The general approach was to place inbound and outbound calls to and from monitored telephones, and verify the recordings. For functionality testing, basic telephony operations such as answer, hold/retrieve, transfer, and conference were exercised on the inbound and outbound calls. For performance testing, a call generator placed inbound calls to monitored telephones over an extended period of time.

### 6.2. Test Results

All feature and performance tests passed. The Verint ULTRA successfully recorded, displayed and replayed the recordings.

There can be at most one service observer on an active call, and a station can be service observed by at most one service observer. This means that when two or more service observed stations (parties) are on the same call, only one of the parties is service observed and therefore recorded. ULTRA will produce call recording records for each monitored party, but only the recording record for the service observed party will contain audio.

When there is a TSAPI or network failure, no call information will be displayed on any active calls or new calls during the failure. During a network failure, it can take up to four minutes before the TSAPI link is re-established. Recording of active calls continues uninterrupted.

Ensure that sufficient MEDPRO resources are available to support the number of Communication Manager API stations, and monitored IP telephones and softphones. Consult the Avaya product documentation for further details.

# 7. Verification Steps

#### 7.1. Avaya

The following steps can ensure that the communication between Avaya Communication Manager and the Avaya Application Enablement Services server is working.

Click on Status and Control  $\rightarrow$  Switch Conn Summary in the AES OAM pages. This summary gives the status of the connection between Avaya Communication Manager and the Avaya Application Enablement Services server. Verify that the Conn State indicates Talking.

OAM Home										
CTI OAM Home	You	are he	re: >	Status and	d Contro	<u>ol &gt; s</u>	witch C	Conn Su	mmary	
<ul> <li><u>Administration</u></li> <li><u>Status and Control</u></li> </ul>	-	Swi	tch C	onnecti	ions S	umm	ary			
Switch Conn Summary Services Summary Maintenance Logs		Switch Conn	Conn State	Since	Online/ Offline	Active CLANs/ Admin'd CLANs	# of MCI Conns	Msgs To Switch	Msgs From Switch	Msg Period
Utilities	-	12/2/2/20		2005-08-		10004000	120		1297 (2)	2.23
▶ <u>Help</u>	۲	8500	Talking	11 06:54:50.0	Online )	1/1	3	210	210	30
Logout	Or	line	Offline	Message	Period		Switch	Connecti	on Detail	s

Click on Status and Control  $\rightarrow$  Services Summary in the AES OAM pages. This summary gives the status of each service.

Αναγα	<u>04</u>	<u>am</u>						
OAM Home								
CTI OAM Home	You are here: > <u>Status and Control</u> > <u>Services Summary</u>							
Administration		Services Summary						
<ul> <li><u>Status and Control</u></li> </ul>								
Switch Conn Summary		Service	Status	Since	Cause			
Services Summary Maintenance	۲	CVLAN Service	ONLINE	2005-08-10 17:05:51	NORMAL			
▶ <u>Logs</u> ▶ <u>Utilities</u>	0	DLG Service	ONLINE	2005-07-11 16:07:43	NORMAL			
▶ <u>Help</u> Loqout	0	TSAPI Service	ONLINE	2005-08-10 13:20:37	NORMAL			
	De	tails						

To test the TSAPI link, click on Utilities  $\rightarrow$  ASAI Test. Select the TSAPI link and execute the test.



Equivalent steps can be taken to check the status of the link on Avaya Communication Manager as follows.

Verify that the Avaya Application Enablement Services server is communicating with the C-LAN on Avaya Communication Manager by using the status aesvcs interface command.

status aesvcs int	erface		
	A	E SERVICES INT!	ERFACE STATUS
Local Node	Enabled?	Number of Connections	Status
clan	yes	1	listening

Verify that the Service State of the TSAPI link is established.

statu	s aesvcs	cti-li	nk			
			AE SERVICES	CTI LINK STAT	US	
CTI	Version	Mnt	AE Services	Service	Msgs	Msgs
Link		Busy	Server	State	Sent	Rcvd
1	4	no	AEServer	established	15	15
<b>3</b>	<b>4</b>	<b>no</b>	<b>AEServer</b>	<b>established</b>	<b>15</b>	<b>15</b>

#### 7.2. Verint

Verint has supplied a variety of tools with the ULTRA solution to provide a means of both monitoring and diagnosing potential issues.

The System Monitor provides a hierarchical view of the status of various systems within the recording solution. This is color-coded at both the node and branch levels – green for OK and red for a problem.

A screenshot of the system monitor is shown below.



The IntelliLink Analyzer provides a view of the CTI link. The attached screenshot shows typical activity for a monitored call.

🖀 IntelliLink Analyzer	
IntelliLink Status Running: Yes Connected to CTI: Yes Switch Specific Connection Status: Switch 1 - Connect (PID 4616) Segments per Hour: 145 Total Failed Devices: 8 Failed Devices: 10002 10003 10004 10005 10005 10005 10006 10007 10008 10009	Queries   Find:   Agent and Trunk   By:   Extension     Extension:     Query Results   Query:
IntelliLink Events C Hide Events  Show Brief Events  14:14:39 Call Callback - Number: 3 Reaso 14:14:39 Call Callback - Number: 4 Reaso 14:14:56 Call Callback - Number: 4 Reaso 14:14:56 Call Callback - Number: 4 Reaso	Show Detailed Events       Expand Event Panel       Clear         on: STARTSESSION       Extension: 10001       Trunk: -1         on: STARTSESSION       Extension: 10000       Trunk: -1         on: ENDSESSION       Extension: 10000       Trunk: -1         on: ENDSESSION       Extension: 10000       Trunk: -1         on: ENDSESSIONANDENDCALL       Extension: 10001       Trunk: -1

### 8. Support

If technical support is required for the Verint ULTRA solution, then contact Verint Technical Support. Full details are available at <u>http://www.verint.com</u>.

# 9. Conclusion

These Application Notes describe the required configuration steps for the Verint ULTRA to successfully interoperate with Avaya Communication Manager. Functionality and performance were successfully validated. The configuration described in these Application Notes has been successfully compliance tested.

### 10. Additional References

This section references the Avaya and Verint ULTRA product documentation that are relevant to these Application Notes.

Avaya product documentation can be found at <u>http://support.avaya.com</u>. Verint product documentation is available on request from Verint <u>http://www.verint.com</u>.

#### ©2005 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by <sup>®</sup> and <sup>TM</sup> are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya Developer*Connection* Program at devconnect@avaya.com.