



Avaya Solution & Interoperability Test Lab

Application Notes for Audentify Record V1.1 with Avaya Communication Manager 2.1 and Avaya Computer Telephony V1.3 – Issue 1.0

Abstract

These Application Notes describe the configuration steps required in order for Audentify Record to successfully interoperate with Avaya Communication Manager 2.1.

Audentify is a Call Recording solution able to capture audio from Communication Manager using a variety of integration mechanisms.

An Avaya S8700 Media Server with an Avaya G600 Media Gateway running Communication Manager 2.1 was used as the hosting PBX. Features and functionality were validated and performance testing was conducted in order to verify operation under light load.

Information in these Application Notes has been obtained through compliance testing and additional technical discussions. Testing was conducted via the *DeveloperConnection* Program at the Avaya Solution and Interoperability Test Lab.

1. Introduction

These Application Notes describe the compliance-tested configuration using an Audentify Record Server and Avaya Communication Manager. They address the external call recording capability of Communication Manager.

Audentify uses the TSAPI capability of Avaya Computer Telephony to monitor extensions on a Communication Manager system.

Audentify Record supports active Station-Side service observation over a T1 trunk as well as passive Trunk-Side recording. Both modes were tested with the configuration shown below.




Figure 1: Tested Avaya Communication Manager System with Audentify Record Server

2. Equipment and Software Validated

Equipment	Software
Avaya S8700 Media Server	CM2.1 load 410.0
Avaya G600 Media Server	N/A
Avaya Computer Telephony Server	V1.3
Avaya P333T Stackable Switch	V4.0.17
Audentify Record Server	R1.1

3. Configure Communication Manager

Different features of Communication Manager need to be configured for the two recording modes to be tested. Please refer to the Administrators Guide for Communication Manager for further details – Avaya Document number 555-233-506 [1]. The specific options are detailed below.

3.1. Passive Trunk-Side Recording

By definition, no specific configuration is required within Communication Manager, since this is intended to monitor an existing and active trunk. However, for completeness, the definition of the passively tapped trunk is included.

There are three main configuration elements for a trunk – DS1 configuration, Signaling Group, and Trunk Group. All three screen shots are shown below:

Display DS1 2a07

Voice System name: Grove - DS1 CIRCUIT PACK	
Location: 02A07	Name: BT 01483 5474xx
Bit Rate: 2.048	Line Coding: hdb3
Signaling Mode: isdn-pri	
Connect: network	
TN-C7 Long Timers? n	Country Protocol: etsi
Interworking Message: PROgress	Protocol Version: b
Interface Companding: alaw	CRC? y
Idle Code: 01010100	
DCP/Analog Bearer Capability: 3.1kHz	
T303 Timer(sec): 4	
Slip Detection? y	Near-end CSU Type: other

Display Signal 91

```
Voice System name: Grove - SIGNALING GROUP

Group Number: 91          Group Type: isdn-pri
Associated Signaling? y    Max number of NCA TSC: 0
Primary D-Channel: 02A0716 Max number of CA TSC: 0
Trunk Group for NCA TSC: 91
Trunk Group for Channel Selection: 91 X-Mobility/Wireless Type: NONE
Supplementary Service Protocol: a
```

Display Trunk 91

```
Voice System name: Grove - TRUNK GROUP

Group Number: 91          Group Type: isdn          CDR Reports: r
Group Name: BT 01483 5474xx/5476xx COR: 1          TN: 1          TAC: 791
Direction: two-way        Outgoing Display? n        Carrier Medium: PRI/BRI
Dial Access? y            Busy Threshold: 255        Night Service:
Queue Length: 0
Service Type: public-ntwrk Auth Code? n            TestCall ITC: rest
Far End Test Line No:

TestCall BCC: 4
TRUNK PARAMETERS
Codeset to Send Display: 6 Codeset to Send National IEs: 6
Max Message Size to Send: 260 Charge Advice: none
Supplementary Service Protocol: a Digit Handling (in/out): enbloc/overlap

Trunk Hunt: cyclical

Incoming Calling Number - Delete: Insert:          Format:
Bit Rate: 1200          Synchronization: async Duplex: full
Disconnect Supervision - In? y Out? n
Answer Supervision Timeout: 0
```

```
TRUNK FEATURES
ACA Assignment? n          Measured: both          Wideband Support? n
Maintenance Tests? y
Data Restriction? n        NCA-TSC Trunk Member: 1
Send Name: y              Send Calling Number: y

Used for DCS? n
Suppress # Outpulsing? n    Format: public
Outgoing Channel ID Encoding: preferred UUI IE Treatment: shared
Maximum Size of UUI IE Contents: 128
Replace Restricted Numbers? n
Replace Unavailable Numbers? n
Send Connected Number: y
Modify Tandem Calling Number? n

Send UUI IE? y
Send UCID? n              BSR Reply-best DISC Cause Value: 31
Send Codeset 6/7 LAI IE? y Dsl Echo Cancellation? n

US NI Delayed Calling Name Update? n

SBS? n Network (Japan) Needs Connect Before Disconnect? n
```

INCOMING CALL HANDLING TREATMENT						
Service/ Feature	Called Len	Called Number	Del	Insert	Per Call CPN/BN	Night Serv
public-ntwrk	6	547400	6	17001		
public-ntwrk	6	547499	6	30004		
public-ntwrk	6	547411	6	18011		
public-ntwrk	6	547402	6	15002		
public-ntwrk	6	547401	6	15001		
public-ntwrk	6	547420	6	10020		
public-ntwrk	6	547421	6	10018		
public-ntwrk	6	547429	6	14970		
public-ntwrk	6	547428	6	14971		
public-ntwrk	6	547600	6	17062		
public-ntwrk	6	547602	6	17002		
public-ntwrk	6	547603	6	17003		
public-ntwrk	6	547474	6	40008		
public-ntwrk	6	547620	6	67001		
public-ntwrk	6	547621	6	60001		
public-ntwrk	6	547622	6	60002		
public-ntwrk	6	547623	6	60003		
public-ntwrk	6	547403	6	93312345		

TRUNK GROUP						
					Administered Members (min/max):	1/4
GROUP MEMBER ASSIGNMENTS					Total Administered Members:	4
Port	Code	Sfx	Name	Night	Sig	Grp
1: 02A0701	TN2464				91	
2: 02A0702	TN2464				91	
3: 02A0703	TN2464				91	
4: 02A0704	TN2464				91	

3.2. Active Line-Side T1 Service Observation

This mode uses a DS1 trunk configured for T1 and a group of 24 extensions configured as off-premises analogue stations. The DS1 configuration and a sample extension (station 13001) are shown below:

Display DS1 2B04

Voice System name: Grove - DS1 CIRCUIT PACK	
Location: 02B04	Name: Line-Side T1
Bit Rate: 1.544	Line Coding: ami-basic
Line Compensation: 1	Framing Mode: d4
Signaling Mode: robbed-bit	
Interface Companding: mulaw	
Idle Code: 11111111	
Slip Detection? n	Near-end CSU Type: other

Display Station 13001

display station 13001		Page 1 of 3
STATION		
Extension: 13001	Lock Messages? n	BCC: 0
Type: DS1FD	Security Code:	TN: 1
Port: 02B0401	Coverage Path 1:	COR: 1
Name: Line-Side T1 Port 01	Coverage Path 2:	COS: 1
	Hunt-to Station:	Tests? n
STATION OPTIONS		
Loss Group: 4		
Off Premises Station? y		
R Balance Network? n		
FEATURE OPTIONS		
LWC Reception: spe	Coverage Msg Retrieval? y	
LWC Activation? y	Auto Answer: none	
LWC Log External Calls? n	Data Restriction? n	
CDR Privacy? n	Call Waiting Indication? y	
Redirect Notification? y	Att. Call Waiting Indication? y	
Per Button Ring Control? n	Distinctive Audible Alert? y	
	Adjunct Supervision? y	
Switchhook Flash? y		
Ignore Rotary Digits? n		
H.320 Conversion? n	Per Station CPN - Send Calling Number?	
Service Link Mode: as-needed		
Multimedia Mode: basic		
MWI Served User Type:		
AUDIX Name:		
Messaging Server Name:	Coverage After Forwarding? s	
	Multimedia Early Answer? n	
Emergency Location Ext: 13001		
SITE DATA		
Room:	Headset? n	
Jack:	Speaker? n	
Cable:	Mounting: d	
Floor:	Cord Length: 0	
Building:	Set Color:	
ABBREVIATED DIALING		
List1:	List2:	List3:
HOT LINE DESTINATION		
Abbreviated Dialing List Number (From above 1, 2 or 3):		
Dial Code:		
Line Appearance: call-appr		

4. Configure the Avaya P333T Stackable Switch

No special configuration of this device is necessary in this configuration.

5. Configure the Avaya Computer Telephony Server

No special configuration of this server is necessary for integration with the Audentify solution.

Since TSAPI is a Client/Server architecture, the only administration required is at the Client (Audentify Server) end of the link.

Anchor is a general purpose PC running Windows NT 4.0 Server and Avaya Computer Telephony V1.3.

6. Configure the Audentify Server

The Audentify Server required slightly different configuration options for the two recording modes to be tested, and rules need to be configured for any recording to take place.

6.1. CTI Configuration

The CTI configuration to access the Avaya CT server is consistent for all modes – mainly containing the credentials for accessing the TSAPI link as well as listing the devices to be monitored. The latter are the DeviceID's. The contents of the "AvayaConnector.cfg" file are shown below:

```
[Default]
StartTime=now
RepeatSecs=10
Cycles=-1

[AvayaConnector]
ServerID=AVAYA#GROVE#CSTA#ANCHOR
LoginID=tsuser
Password=tsuser
LoggerHost=localhost
LoggerPort=43666
DeviceIDs=10018,10016,10014,16001
ChannelMappings=ChannelMapping.cfg
```

6.2. Agent Configuration

Please note that this refers to an agent as far as Audentify is concerned – it relates to an Avaya Call Centre agent by virtue of the User PBXID. This mechanism is also used by Audentify to group related agents. A sample screen shot showing Agent ID 15001 is shown below:




Figure 2: Audentify Agent Configuration

6.3. Rule Configuration

Rules allow the recording algorithm to be defined within Audentify. For testing, very simple rules were defined for recording 100% of calls for agent1 (x15001) and agent2 (x15002) regardless of duration or direction. However, the logic behind recording rules can be far more complex. A screen shot showing the rules used for testing is shown below:




Figure 3: Audentify Rule Configuration – Part One

Since the screen did not quite contain all of the defined rules, the lower half is shown below:




Figure 4: Audentify Rule Configuration – Part Two

6.4. Rule Testing

A simple inbound call was made to one of the monitored agents to validate the operation of the rules and the Audentify system in general. A screenshot of the successfully recorded call is shown below:




Figure 5: Audentify Rule Test

6.5. Sample Recording Retrieval

Having made several calls as defined in the Test Plan, a sample recording retrieval was carried out to validate the data stored for each recording. A screenshot of the successfully recorded calls is shown below:




Figure 6: Audentify Recording Retrieve

7. Interoperability Compliance Testing

7.1. General Test Approach

Testing included validation of correct operation of typical Voice Recording functions including Inbound, Outbound, Blind Transfer, Attended Transfer, and Conference calls. These tests were repeated for both modes of recording. Light load testing and link integrity testing was also carried out.

7.2. Test Results

All tests passed.

8. Verification Steps

The following verification steps can be used to isolate problems in the field and to ensure that the CTI link is correctly passing data between the various components of the solution. Please note that it is a requirement of the Compliance Test that a fully operational Avaya CT server be provided prior to testing. As such, the operation of the Avaya CT server is assumed to be in service. The section verifies the connectivity from the Avaya CT server to the Audentify Record Server.

1. Avaya CT is shipped with a very simple TSAPI application called “TSTEST”. Whilst this utility only allows connection to a server and the origination of a single call, it is invaluable in verifying CTI connectivity. There is also a small application called “TSSPY” which can be used to trace the messages to and from the Avaya CT Server. These two in conjunction are able to ensure that the CTI link is operating correctly. Hence the only required verification step for CTI is to use “TSTEST” to initiate a call from one known physical extension to another. Having made the CTI call, ensure that the physical devices are indeed trying to call each other, manually answer the call, and then use “TSTEST” to clear the call.
2. Audentify Record has a CTI Message tracing capability to aid fault diagnosis in the field. Generate a simple inbound test call to a monitored station and ensure that the Message Trace contains a set of events related to the test call. This message trace also contains information as to whether the call should be stored or not.
3. The status of the Line-Side T1 extensions, if this recording mode is being used, can be tested from Communication Manager as with a conventional station. If the status is “disconnected”, then the T1 trunk is not operating correctly. The “Test DS1 xxxx” command can be used to check the DS1 card is connected correctly – the first test is physical connectivity. Please refer to the Communication Manager manuals for details of other error messages that may be displayed when using this command. Please note that some tests may either fail or be aborted due to the status of the extensions – these messages may be of little or no significance in this configuration.

9. Support

If technical support is required for the Audentify Record server, then please contact their Technical Support Manager, Tom Blackie

Email: tomb@audentify.com

Phone: +44 1223 448000

10. Conclusion

These Application Notes describe the configuration steps required for Audentify Record to successfully interoperate with Avaya Communication Manager 2.1. An Avaya S8700 Media Server with an Avaya G600 Media Gateway running Communication Manager 2.1, together with Avaya Computer Telephony V1.3, was used as the hosting environment. Features and functionality were validated and performance testing was conducted in order to verify operation under light load. The configuration described in these Application Notes has been successfully compliance tested.

11. Additional References

[1] Administrators Guide for Communication Manager (Doc ID: 555-233-506) can be found at <http://support.avaya.com>.

[2] Installation Guide for Avaya Computer Telephony can be also be found at <http://support.avaya.com>.

©2004 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya Developer*Connection* Program at devconnect@avaya.com.