



## **Avaya Solution & Interoperability Test Lab**

---

# **Application Notes for configuring Oak Telecom's reportX with Avaya Aura<sup>®</sup> Communication Manager R6.0.1 - Issue 1.0**

### **Abstract**

These Application Notes describe the configuration steps for provisioning Oak Telecom's reportX Call Detail Recording solution to successfully interoperate with Avaya Aura<sup>®</sup> Communication Manager R6.0.1. The Oak Telecom solution consists of a Call Detail Recording server based on the logging of outgoing, incoming, internal and missed calls data reported by the PBX, to manage captured data and generate reports.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

# 1. Introduction

These Application Notes describe the configuration steps required for reportX from Oak Telecom to successfully collect call detail recording records from Avaya Aura® Communication Manager R6.0.1 over TCP/IP. Oak Telecom reportX Call Logging (reportX) is a call management and reporting software package designed to report on the phone activity of a business. Oak Telecom reportX collects, stores and processes these Call Detail Recording (CDR) records to provide usage analysis, call costing and billing capabilities. Avaya Aura® Communication Manager (Communication Manager) can generate call detail records for intra-switch calls, inbound trunk calls and outbound trunk calls. In addition, split records can be generated for transferred and conference calls. Oak Telecom reportX can support any CDR format provided by Communication Manager. Oak Telecom reportX creates a custom PBX configuration file to accurately parse the CDR data. For the compliance testing, a customized format was used.

## 2. General Test Approach and Test Results

The general test approach was to manually place intra-switch calls, inbound trunk calls, outbound trunk calls, conference calls, transferred calls, and forwarded calls to and from telephones controlled by Communication Manager and verify that reportX collects the CDR records and properly classifies and reports the attributes of the call. For serviceability testing, logical links were disabled/re-enabled.

### 2.1. Interoperability Compliance Testing

The principle objective of Interoperability Compliance testing is to provide assurance to the potential customers that the tested products operate as specified and can interoperate in an environment similar to the one that will be deployed at a customer's premises. Performance and load testing is outside the scope of the compliance testing. The compliance testing is concerned with verifying that the addition of reportX does not interfere with the operation of Communication Manager in any way.

#### 2.1.1. Avaya feature Interaction Verification

This consists of the verification of the response of the reportX to the Communication Manager for the following call types:

- **Inbound calls** – Test CDR records for inbound calls to the Communication Manager from PSTN callers.
- **Outbound calls** – Test CDR records for outbound calls from the Communication Manager to PSTN callers.
- **Hold/Transferred calls** – Test CDR records for calls transferred to PSTN callers.
- **Conference calls** - Test CDR records for calls in conference between the Communication Manager and PSTN callers.
- **Forwarded calls** – Test CDR records for calls made to deskphones that are forwarded to the PSTN.

- **Failover of reportX** - The behaviour of reportX under different failure conditions will also be observed

## 2.2. Test Results

All tests passed successfully. No errors or performance issues were observed on Communication Manager.

**Note:** Testing in all cases of this document consisted of only H.323 signalling on the Communication Manager, when SIP deskphones were used CDR information was captured but a second CDR entry for the communication between the Session Manager and Communication Manager was observed; therefore, SIP deskphones were not included in the compliance testing.

**Note:** Information on internally transferred and conference calls were reported as internal calls.


## 2.3. Support

Support from Avaya is available at <http://support.avaya.com>. Technical support for reportX can be obtained as shown below.

Oak Telecom  
Unit 7 Albany Park,  
Cabot Lane, Poole,  
Dorset BH17 8BX  
United Kingdom  
Tel: +441202607000  
Email: [support@oak.co.uk](mailto:support@oak.co.uk)  
Web Support: <http://help.oak.co.uk>

### 3. Reference Configuration

**Figure 1** shows the network topology during compliance testing. Oak Telecom's reportX Server collects CDR records from the Communication Manager and presents the information obtained to users on the LAN via a Client/Server session.



**Figure 1: Connection of Oak Telecom reportX Call Logging and Avaya Aura® Communication Manager R6.0.1.**

## 4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided:

Equipment Description	Software Release
Avaya S8800 Server	Avaya Aura <sup>®</sup> Communication Manager R6.0.1 SP3
Avaya S8800 Server	Avaya Aura <sup>®</sup> System Manager R6.1 SP4
Avaya 96xx Series H.323 Set	96xx H.323 Release 3.1 SP2
Avaya 24xx Series Digital Set	N/A
Oak Telecom reportX Call Logging	reportX Call Logging Release 9.0.8.0

## 5. Configuration of Avaya Aura® Communication Manager

Configuration of Communication Manager is performed through Avaya Site Administration supporting System Administration Terminal (SAT). An SSH session to the IP address of the Communication Manager initiates the console connection.

**Note:** The configuration of Communication Manager for call routing is outside the scope of this document. It is assumed that a full working system is already installed. Included below are the changes necessary in order to ensure CDR records are being produced correctly by the Communication Manager. For all other provisioning information, such as administering Communication Manager, refer to product documentation in **Section 9** of these Application Notes.

### 5.1. Add CDR Server to Node Names IP

Add the IP address of the CDR server into the **IP NODE NAMES**. Type **change node-names ip** to access the node names and add the server **Name** and **IP Address** as shown below.

change node-names ip		IP NODE NAMES
Name	IP Address	
CLAN	192.168.30.80	
Medpro	192.168.30.81	
SessionManager	192.168.30.101	
default	0.0.0.0	
gateway	192.168.30.1	
procr	192.168.30.92	
procr6	::	
ReportX_Server	192.168.30.22	

### 5.2. Add CDR Service as an IP Service

Add the CDR service into IP Services by typing **change ip-services**. Note the following as this information may be needed when setting up the reportX Server.

- **Local Node** is **CLAN**
- **Remote Node** is that of the **CDR\_Server** entered as it was configured above.
- **Service Type** is **CDR1**
- **Remote Port** number in this example shown as **9001** but can be any free port number.

change ip-services		Page 1 of 3			
		IP SERVICES			
Service Type	Enabled	Local Node	Local Port	Remote Node	Remote Port
CDR1		CLAN	0	ReportX_Server	9001

### 5.3. Configure CDR parameters

Type **change system-parameters cdr**. Ensure all the fields are as shown below on **Page 1** of **system-parameters cdr**. Note the **Primary Output Endpoint** is that of the service type added in **Section 5.2**.

change system-parameters cdr		Page 1 of 2
CDR SYSTEM PARAMETERS		
Node Number (Local PBX ID):		CDR Date Format: month/day
Primary Output Format: customized	Primary Output Endpoint: CDR1	
Secondary Output Format:		
Use ISDN Layouts? n	Enable CDR Storage on Disk? n	
Use Enhanced Formats? n	Condition Code 'T' For Redirected Calls? y	
Use Legacy CDR Formats? y	Remove # From Called Number? n	
Modified Circuit ID Display? n	Intra-switch CDR? y	
Record Outgoing Calls Only? n	Outg Trk Call Splitting? y	
Suppress CDR for Ineffective Call Attempts? n	Outg Attd Call Record? y	
Disconnect Information in Place of FRL? n	Interworking Feat-flag? n	
Force Entry of Acct Code for Calls Marked on Toll Analysis Form? n		
Calls to Hunt Group - Record: member-ext		
Record Called Vector Directory Number Instead of Group or Member? n		
Record Agent ID on Incoming? n	Record Agent ID on Outgoing? y	
Inc Trk Call Splitting? n		
Record Non-Call-Assoc TSC? n	Call Record Handling Option: warning	
Record Call-Assoc TSC? n	Digits to Record for Outgoing Calls: dialed	
Privacy - Digits to Hide: 0	CDR Account Code Length: 15	

Ensure that all **Data Item Length** entries are the same as outlined below on **Page 2** of **system-parameters cdr**.

change system-parameters cdr		Page 2 of 2
CDR SYSTEM PARAMETERS		
Data Item - Length	Data Item - Length	Data Item - Length
1: date - 6	17: in-trk-code - 4	33: line-feed - 1
2: space - 1	18: space - 1	34: -
3: time - 4	19: in-crt-id - 3	35: -
4: space - 1	20: space - 1	36: -
5: sec-dur - 5	21: out-crt-id - 3	37: -
6: space - 1	22: space - 1	38: -
7: cond-code - 1	23: ppm - 5	39: -
8: space - 1	24: space - 1	40: -
9: code-used - 4	25: isdn-cc - 11	41: -
10: space - 1	26: space - 1	42: -
11: code-dial - 4	27: attd-console - 2	43: -
12: space - 1	28: space - 1	44: -
13: dialed-num - 18	29: vdn - 5	45: -
14: space - 1	30: space - 1	46: -
15: clg-num/in-tac - 10	31: acct-code - 15	47: -
16: space - 1	32: return - 1	48: -
Record length = 117		



## 5.4. Enable Missed and Internal Calls

To allow missed calls to appear on the CDR reports, set **CDR Reports** to **r** in the trunk group used for outgoing/incoming calls. Type **change trunk-group x** where **x** is the number of the incoming/outgoing trunk group.

<b>change trunk-group 9</b>		Page 1 of 21	
TRUNK GROUP			
Group Number: 9	Group Type: isdn	<b>CDR Reports: r</b>	
Group Name: reportX	COR: 1	TN: 1	TAC: *19
Direction: two-way	Outgoing Display? n	Carrier Medium: PRI/BRI	
Dial Access? y	Busy Threshold: 255	Night Service:	
Queue Length: 0			
Service Type: tie	Auth Code? n	TestCall ITC: rest	
	Far End Test Line No:		
TestCall BCC: 4			

To enable intra-switch calls to be recorded, type **change intra-switch-cdr** and add the **Extension** numbers of the sets that are to be recorded for internal calls.


<b>change intra-switch-cdr</b>		Page 1 of 3	
INTRA-SWITCH CDR			
	Assigned Members: 8	of 5000 administered	
<b>Extension</b>	Extension	Extension	Extension
2000			
2001			
2002			
2010			
2011			
2012			
4000			
4001			

## 6. Configuration of Oak Telecom's reportX Server


The configuration information provided in this section describes the steps required to set up reportX to collect CDR records generated over a TCP/IP link to Communication Manager. For all other provisioning information, such as reportX software installation, refer to Oak Telecom reportX product documentation in **Section 9** of these Application Notes.

### 6.1. Configuration of Oak Telecom's reportX software to correctly interoperate with Avaya Aura® Communication Manager


On the reportX PC navigate to **Start → Programs → Oak Telecom → report → Setup** as shown below.




Alternatively, this Setup can be launched from the Quick Launcher as shown below. Click on the blank icon in the **QUICK LAUNCH** and select **Comms Suite Setup**.



Select **Supervisor** for the **Username** and enter the appropriate **Password**. Click **OK**.



From the **Standard Settings** section in the left pane, select **Telephone System** to bring up the sites configured. All default installations will be provided with a default site for configuration. Right-click on the default site and **Edit** this site as shown below.



Under the **Call Management** tab, select the **Telephone System** tab and configure the site details as shown below.

- **Site No** Will be set to 1 if this is the first site to be configured.
- **Short Name** Enter any value that describes the site being configured.
- **Name** Enter the full name of the site being configured.
- **Area Code** Enter the local area code that is specific to the site.

The screenshot shows a software window titled "Site Details" with a tree view on the left containing "All Sites" and "Avaya". The "Avaya" folder is expanded, showing a sub-tabbed interface. The "Call Management" tab is active, and within it, the "Telephone System" sub-tab is selected and highlighted with a red rectangle. The "Telephone System" sub-tab contains a list of configuration categories on the left: "Data Collection", "Translation", "Costing", "PBX Integration", and "Other". The main area of the "Telephone System" sub-tab displays the following configuration fields:

Site No	1	
Short Name	ACM	
Name	Avaya Aura Communication Server	
Area Code	091	Galway


At the bottom right of the window, there are two buttons: "OK" (with a green checkmark icon) and "Cancel" (with a red X icon).

Under the **Data Collection** tab, change the collection type by clicking on the highlighted button below.


The screenshot shows the 'Site Details' dialog box with the 'Call Management' tab selected. The 'Data Collection' section is highlighted in the left sidebar. The main area shows the 'Collection Type' as 'TIPServerPort', which is highlighted in yellow. A red box highlights the ellipsis button next to the 'Collection Type' field. Below this, the 'Description' is 'IP Server Port Collector' and the 'BPL Version' is '4.26.0.0'. The 'Settings' section lists: Enhanced Logging=False, Ticker Period in Minutes=0, Data Packet Format=TEXT, Switch Port=9001, and Use ReadIn Function reading from client=true. There is a 'Configure' button. At the bottom, there is a 'TCP/IP Replication' checkbox and a 'Collection Fail Safes' section with 'IP Ping Interval' set to 10000 and 'No Data reconnect' set to 5. The 'OK' and 'Cancel' buttons are at the bottom right.

Section	Field	Value
Data Collection	Site Directory	\\AACC6COR\aiOffice\Call Data\Site1\
	Collection Type	TIPServerPort
	Description	IP Server Port Collector
	BPL Version	4.26.0.0
	Settings	Enhanced Logging=False Ticker Period in Minutes=0 Data Packet Format=TEXT Switch Port=9001 Use ReadIn Function reading from client=true
Collection Fail Safes	IP Ping Interval	10000
	No Data reconnect	5

Select **IP Server** as the **Collector** and double-click **IP Server** to select it.



Press **Configure**, as shown below, in order to change the port to listen for CDR records. Note that this port number will be the same as the port number configured in **Section 5.2**.




Under the **Translation** tab, change the following in order to connect to the Communication Manager.


- **Manufacturer** Select **AVAYA** from the drop down menu.
- **Device** Select **ACM** from the drop down menu.
- **Translator (VCE)** Select **AVAYA DEFINITY OAK FORMAT**.

The screenshot shows a software window titled "Site Details" with two tabs: "Call Management" and "Call Recording". The "Call Management" tab is active. On the left, there is a vertical menu with options: "Telephone System", "Data Collection", "Translation" (highlighted with a red box), "Costing", "PBX Integration", and "Other". The main area of the window displays the configuration for the "Translation" tab. It includes three dropdown menus: "Manufacturer" set to "AVAYA", "Device" set to "ACM", and "Translator (VCE)" set to "AVAYA DEFINITY OAK FORMAT". These three dropdowns are grouped together and highlighted with a red box. Below these is a text area labeled "Translator Authors comments" containing the text "No Description provided". At the bottom right of this section is a button labeled "Refresh VCE Library". At the very bottom of the window are two buttons: "OK" (with a green checkmark icon) and "Cancel" (with a red X icon).

Once all the details above are filled in correctly, click **OK** at the bottom right of the screen as shown below. This will open a new window labeled **Confirm**, click **Yes** on this window.




A system window opens prompting the user to save changes. Click **Yes** as highlighted below to save all changes made in this section.





Once the changes are saved, a window automatically opens prompting the restart of all reportX services. Click on **Restart All** and then **OK** as highlighted below.



## 7. Verification Steps

The following steps can be taken to ensure that the Communication Manager is sending CDR data and to show that the reportX server is receiving this data and processing it properly.


### 7.1. Verify that CDR data is being sent by the Avaya Aura® Communication Manager

Type **status cdr-link**, this brings up a page showing the **Link State** as either up or down. Observe as shown below the **Link State** should be **up**.

<b>status cdr-link</b>	
CDR LINK STATUS	
Primary	Secondary
<b>Link State: up</b>	CDR not administered
Date & Time: 2011/11/02 11:11:02	0000/00/00 00:00:00
Forward Seq. No: 0	0
Backward Seq. No: 0	0
CDR Buffer % Full: 0.00	0.00
Reason Code: OK	


### 7.2. Verify Oak telecom Services are running

Open a web session to <http://<servername>:9595> in order to view the services as highlighted below.




### 7.3. Verify that CDR data is being received by Oak Telecom's reportX Server

Log onto the reportX server and check that raw CDR data is being received into the Site1 Folder. Open the folder called Site1 located in **C:/Program Files (x86)/Oak Telecom/aiOffice/Call Data**. This should contain a **COL File** as is highlighted below.




The COL File should contain information on recent calls as shown below. This will be in raw format and is not expected to be fully understandable.




## 7.4. Verify that Oak Telecom's reportX is producing reports on CDR information correctly

Open the reportX client software Report09 in order to view reports. Navigate to **Start → Programs → Oak Telecom → report → report09** as shown below.




Alternatively, reports can be accessed from the Quick Launcher as shown below. Click on the blank icon in the **QUICK LAUNCH** and select **report**.




Select **Supervisor** for the **Username** and enter the appropriate **Password**. Click **OK**.




Click on **Traffic Reports** and select **Itemised By Time** as highlighted below. Before the report is run, click on **Custom** to include internal calls in the report.



Type **int(o)** into the **Custom Criteria** window as shown below.




Click on **Run** to run the report as highlighted below.





An example of such a report is shown below.

Run on: 7 December 2011 12:02:56 Page 1



## Itemised By Time

Site : (1)Avaya Aura Communication Server. Calls from Wed Dec 07 2011 to Wed Dec 07 2011. Calls from 00:00 to 23:59 each day. Internal Calls: Original.

Date	Time	Site Code	Type Of Call	From Extn/Line	To Extn/Line	Duration HH:MM:SS	Ring Secs	Answ Call	Trans Call	Phone Number	Account Code	Cost €
Dec 07 11	12:18:00	ACM	Int	E 2011	E 2012	00:00:08	0	Yes	No			€0.00
Dec 07 11	12:18:00	ACM	Int	E 2010	E 2011	00:00:20	0	Yes	No			€0.00
Dec 07 11	12:19:00	ACM	Out	E 2010	L	00:00:17	0	---	No	2011		€0.00
Dec 07 11	12:19:00	ACM	Out	E 2011	L	00:00:10	0	---	No	2012		€0.00
Dec 07 11	12:26:00	ACM	Int	E 2011	E 2012	00:00:12	0	Yes	No			€0.00
Dec 07 11	12:26:00	ACM	Int	E 2010	E 2011	00:00:11	0	Yes	No			€0.00
Dec 07 11	12:27:00	ACM	Out	E 2011	L	00:00:16	0	---	No	2012		€0.00
Dec 07 11	12:27:00	ACM	Out	E 2010	L	00:00:20	0	---	No	2011		€0.00
Total Calls		8										



## 8. Conclusion

As illustrated in these Application Notes, Oak Telecom's reportX can be configured to successfully interoperate with Avaya Aura® Communication Manager R6.0.1. All call types generated a CDR record and was reported on correctly by the reportX Server.

## 9. Additional References

This section references documentation relevant to these Application Notes. The Avaya product documentation is available at <http://support.avaya.com> where the following documents can be obtained.

- [1] *Administering Avaya Aura® Communication Manager, Document ID 03-300509, June 2010.*
- [2] *Avaya Aura® Communication Manager Feature Description and Implementation, Document ID 555-245-205, June 2010.*
- [3] *Maintenance Commands for Avaya Aura® Communication Manager, Branch Gateways and Servers Document ID 03-300431, May 2011.*

All information on the product installation and configuration for Oak Telecom reportX can be found at <http://help.oak.co.uk>. This is an online help which contains documentation and video guides supporting all Oak Telecom's products.

---

**©2012 Avaya Inc. All Rights Reserved.**

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at [devconnect@avaya.com](mailto:devconnect@avaya.com).