

Avaya Solution & Interoperability Test Lab

Application Notes for JPL BL-054MS+P USB Cable and QD Connector with JPL-Element-TT3 headset, using JPL Gateway with Avaya Workplace Client for Windows - Issue 1.0

Abstract

These Application Notes describe the configuration steps required to integrate JPL BL-054MS+P USB Cable and QD Connector with the JPL-Element-TT3 headset, using JPL Gateway software with Avaya Workplace Client for Windows.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as any observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

1. Introduction

The JPL BL-054MS+P USB Cable and QD Connector with JPL-Element-TT3 headset, using JPL Gateway software, allows connectivity to Avaya Workplace Client for Windows (hereafter referred to as Avaya Workplace) via a USB-A interface on the PC.

The JPL BL-054MS+P USB Cable and QD Connector, using JPL Gateway software, can be used with other JPL headsets, as detailed in Attachment 1. For additional information or support, contact JPL as noted in Section 2.3.

2. General Test Approach and Test Results

The interoperability compliance test included feature and serviceability testing. The feature testing focused on placing calls with Avaya Workplace, answering and ending calls using the call control button on the headset, and verifying two-way audio. The call types include calls to voicemail, local extensions, and the PSTN. Call hold and resume, mute and un-mute, and volume are also tested.

The serviceability testing focused on verifying the usability of the headset solution after restarting Avaya Workplace, restarting the PC, and reconnecting the USB cable to the PC.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in these DevConnect Application Notes included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with these Application Notes, the interface between Avaya systems and endpoints utilized enabled capabilities of TLS/SRTP.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya's formal testing and Declaration of Conformity is provided only on the headsets/handsets that carry the Avaya brand or logo. Avaya may conduct testing of non-Avaya headset/handset to determine interoperability with Avaya phones. However, Avaya does not conduct the testing of non-Avaya headsets/handsets for: Acoustic Pressure, Safety, Hearing Aid Compliance, EMC regulations, or any other tests to ensure conformity with safety, audio quality, long-term

reliability or any regulation requirements. As a result, Avaya makes no representations whether a particular non-Avaya headset will work with Avaya's telephones or with a different generation of the same Avaya telephone.

Since there is no industry standard for handset interfaces, different manufacturers utilize different handset/headset interfaces with their telephones. Therefore, any claim made by a headset vendor that its product is compatible with Avaya telephones does not equate to a guarantee that the headset will provide adequate safety protection or audio quality.

2.1. Interoperability Compliance Testing

All test cases were performed manually. The following features were verified:

- Placing calls to the voicemail system. Voice messages were recorded and played back to verify that the playback volume and recording level were good.
- Placing calls to internal extensions to verify two-way audio.
- Placing calls to the PSTN to verify two-way audio.
- Answering and ending calls using the call button on the headset and the soft button on Avaya Workplace.
- Using the call button on the headset and the soft button on Avaya Workplace to hold and resume the audio.
- Using the volume buttons on the headset to adjust the audio volume.
- Using the mute button on the headset and the soft button on Avaya Workplace to mute and un-mute the audio.
- Verifying incoming call notification on cable.
- Verifying call ended notification on cable.

The serviceability testing focused on verifying the usability of the headset solution after restarting Avaya Workplace, restarting the PC, and reconnecting the USB cable to the PC.

2.2. Test Results

JPL BL-054MS+P USB Cable and QD Connector does not support Call Control (answering and hanging-up calls) by using the cable with this solution. Only two-way audio, mute/unmute and volume control were verified successfully.

2.3. Support

For support on this JPL headset solution, contact JPL at:

■ Phone: +44(0)1258 820100

• Website: http://www.jpltele.com/

3. Reference Configuration

Figure 1 illustrates the test configuration used to verify the JPL BL-054MS+P USB cable and QD connector with JPL-Element-TT3 headset using JPL Gateway with Avaya Workplace. The configuration consists of Avaya Aura® Communication Manager running on a virtualized server with an Avaya G430 Media Gateway. Avaya Aura® Session Manager was used as the registrar/proxy for Avaya Workplace as a SIP softphone and Avaya Aura® System Manager was used to configure Session Manager. Avaya Aura® Messaging was used as the voicemail system. Avaya Aura® Media Server provided the audio media processing. Avaya Session Border Controller for Enterprise was used to complete a SIP trunk connection to simulate a PSTN connection to the Enterprise solution. The JPL Gateway was installed on the PC together with Avaya Workplace. The JPL cable is connected via USB to the PC.




Figure 1: Test Configuration

4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided.

Equipment/Software	Release/Version		
Avaya Aura® Communication Manager	8.1.3		
Avaya G430 Media Gateway	41.24.0		
■ MGP	41.34.0		
Avaya Aura® System Manager	8.1.3		
Avaya Aura® Session Manager	8.1.3		
Avaya Aura® Media Server	8.0.2.138		
Avaya Aura® Messaging	7.1 SP2		
Avaya Workplace Client running on Windows 10 Pro	3.12		
JPL BL-054MS+P with	0254		
JPL-Element-TT3 Headset	0254		
JPL Gateway Software	2.8.1		

5. Configure Avaya Aura® Communication Manager

The information provided in this section describes the verification of Communication Manager System Capacity for this solution.

It is implied a working Communication Manager system is already in place, including dial plans and SIP trunks to a Session Manager. For all other provisioning information such as initial installation and configuration, please refer to the product documentation in **Section 11**.

5.1. Verify System Capacity

Using Avaya Site Administrator Emulation Mode, enter the **display system-parameters customer-options** command to determine the values of user license for **Maximum Off-PBX Telephones** allowed in the system. One OPS station is required per SIP User.

```
display system-parameters customer-options
                                                                                              1 of 12
                                          OPTIONAL FEATURES
      G3 Version: V18
                                                                Software Package: Enterprise
        Location: 2
                                                                 System ID (SID): 1
                                                                 Module ID (MID): 1
        Platform: 28
                                                                             USED
                                    Platform Maximum Ports: 81000 385
                                         Maximum Stations: 41000 186
                                 Maximum XMOBILE Stations: 41000
                    Maximum Off-PBX Telephones - EC500: 41000

Maximum Off-PBX Telephones - OPS: 41000

Maximum Off-PBX Telephones - PBFMC: 41000

Maximum Off-PBX Telephones - PVFMC: 41000

Maximum Off-PBX Telephones - SCCAN: 0
                                                                                    1
                                                                                   33
                                                                                    0
                                                                                   0
                                                                                  0
                           Maximum Survivable Processors: 313
                                                                                    2
          (NOTE: You must logoff & login to effect the permission changes.)
```

On Page 2 of the system-parameters customer-options form, verify that the number of Maximum Administered SIP Trunks and Maximum Concurrently Registered IP Stations supported by the system is sufficient.


If there is insufficient capacity in either one of these parameters, contact an authorized Avaya sales representative.

display system-parameters customer-options		Page	2 of	12	
OPTIONAL FEATURES					
IP PORT CAPACITIES		USED			
Maximum Administered H.323 Trunks:	12000	90			
Maximum Concurrently Registered IP Stations:	18000	17			
Maximum Administered Remote Office Trunks:	12000	0			
Max Concurrently Registered Remote Office Stations:	18000	0			
Maximum Concurrently Registered IP eCons:	414	0			
Max Concur Reg Unauthenticated H.323 Stations:	100	0			
Maximum Video Capable Stations:	41000	0			
Maximum Video Capable IP Softphones:	18000	2			
Maximum Administered SIP Trunks:	40000	38			
Max Administered Ad-hoc Video Conferencing Ports:	24000	0			
Max Number of DS1 Boards with Echo Cancellation:	999	0			
(NOTE: You must logoff & login to effect the permission changes.)					

6. Configure Avaya Aura® Session Manager


This section describes aspects of the Session Manager configuration required for Avaya Workplace to register. It is assumed that the Domains, Locations, SIP entities, Entity Links, Routing Policies, Dial Patterns and Application Sequences have been configured where appropriate for Communication Manager, Session Manager and Aura® Messaging.

Session Manager is managed via System Manager. Using a web browser, access https://<ip-addr of System Manager>/SMGR. In the Log On screen, enter appropriate User ID and Password and click the Log On button.



6.1. Verify Session Manager Ports for SIP endpoint registration

Each Session Manager Entity must be configured so that the SIP endpoint can register to it. From the home page, under **Elements**, click **Routing** \rightarrow **SIP Entities** (not shown) and select the Session Manager entity used for registration. Make sure that **TCP**, **UDP** and **TLS** entries are present under **Listen Ports**. During the compliance test, Avaya Workplace registered to the Session Manager using TLS transport.




6.2. Add SIP User

The addition of SIP User will not be detailed here. Refer to details in adding user in the administration document for Avaya Aura® Session Manager in **Section 11**.


7. Configure Avaya Workplace Client for Windows

Avaya Workplace is a SIP softphone application that provides users with access to Unified Communications (UC) services. This section shows how to configure Avaya Workplace to use with the JPL BL-054MS+P cable.

From Avaya Workplace, navigate to **Settings** → **User Preferences** → **Audio/Video**.



Select **Headset Microphone** (2- **BL-054**) for *Microphone* and **Headset Earphone** (2 – **BL-054**) for *Speaker* $^{\triangleleft}$ as shown below. It is optional for *Ringing on incoming calls* $^{\triangle}$ to be set.



8. Configure JPL BL-054MS+P Solution

This section covers the steps to integrate JPL BL-054MS+P cable with Avaya Workplace, including:

- Install the JPL Gateway software
- Connect JPL cable

Note: After successfully performing this procedure, the JPL BL-054MS+P USB cable and QD connector will be detected in Avaya Workplace as described in **Section 7**.


8.1. Install the JPL Gateway Software

JPL Gateway software can be obtained from JPL support portal at https://www.jpltele.com/default.aspx. Installation of the software is done through executing the setup file and following the prompt.

8.2. Connect JPL Cable

Plug the JPL BL-054MS+P USB cable into the USB-A port of the PC and the other end QD connector to the headset. The device drivers will automatically be installed.

Open the JPL Gateway program installed on the PC. It shows the **Device ready for use** for the **BL-054**.




9. Verification Steps

This section verifies that the JPL BL-054MS+P USB cable has been successfully integrated with Avaya Workplace.

- 1. Open the JPL Gateway program to verify that the JPL cable has been successfully connected for use with Avaya Workplace as in **Section 8.2**.
- 2. Make incoming and outgoing calls and verify that calls can be established with two-way audio. For incoming calls, answer the call with the Avaya Workplace.
- 3. End the call by hanging up on the Avaya Workplace.
- 4. Verify also that user is able to remotely control call functions such as mute/un-mute, hold/resume and adjust the volume on the Avaya Workplace. Similarly, verify the same thing on the JPL cable (see diagram below).

Note: JPL BL-054MS+P USB cable does not support call control functions as mentioned in **Section 2.2**. Call answer/end button will not work in this case.



10. Conclusion

These Application Notes describe the configuration steps required to integrate JPL BL-054MS+P USB Cable and QD Connector using JPL Gateway with Avaya Workplace Client for Windows. All test cases were executed with observations noted in **Section 2.2**.

11. Additional References

This section references the Avaya and JPL documentation that are relevant to these Application Notes.

The following Avaya product documentation can be found at http://support.avaya.com.

- [1] Administering Avaya Aura® Communication Manager, Release 8.1.x, Issue 6, Mar 2020
- [2] Planning for and Administering Avaya IXTM Workplace Client for Android, iOS, Mac and Windows, Sep 25, 2020.
- [3] Using Avaya IXTM Workplace Client for Android, iOS, Mac, and Windows, Aug 4, 2020.
- [4] Administering Avaya Aura® Session Manager, Release 8.1.x, Issue 6, Aug 2020.

The following JPL documentation can be found at http://www.jpltele.com/. [1] *JPL BL-054MS+P Data Sheet*.

©2021 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and TM are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.

ATTACHMENT 1

Declaration of Conformity - Wired Headsets



Company: JPL Telecom Ltd

Address: Units 1& 2, Church Close Business Park, Church Close, Todber,

Sturminster Newton, Dorset, DT10 1JH. England.

Hereby declare that all the JPL headsets listed herewith, to which this declaration relates, have the technical specification as given below:

Technical Specification:

Microphone: Impedance:

 $2.2k\Omega$

Sensitivity:

-32dB ± 3dB at 1kHz Bi-directional

Directivity: Frequency Range:

 $50Hz\sim20kHz\pm6dB$ Less than 3%

Power Supply:

3V DC

S/N Ratio:

Distortion:

More than 58dB

Speaker:

Impedance: $150\Omega \pm 15\%$ at 1kHz

Sensitivity: 93 ± 3dB at 1kHz 60mV Input

Max Input Power: 100mV

Frequency Range: 100Hz~6800Hz

Distortion: Less 3% at 1kHz 60mV

JPL Wired Headsets:

JPL-400 JPL-401S JPL-100 JPL-402S JPL-501S

JPL-502S JPL-612 JPL Element TT3 JPL-611 JPL-Connect |

JPL Cables:

BL-054MS+P (Revision: 254) BL-09+P

JPL Connector Software:

JPL Gateway Software (Version: 2.8.1)

JPL Telecom Ltd. also hereby declare that:

• The JPL BL-054MS+P USB QD connector cable identified above is used by all of the JPL wired headsets listed in this letter in combination with the specified JPL Gateway Software to connect with Avaya Workplace Client for Windows.

• The JPL BL-09+P cable identified above is used by **all of the JPL wired headsets** listed in this letter to connect to the Avaya J100 Series IP Phones.

James Clarke

CEO

20th October 2020