



## **Avaya Solution & Interoperability Test Lab**

---

# **Application Notes for EPOS Connect, EPOS BTD 800 Dongle and EPOS ADAPT 200 Series Bluetooth Headset with Avaya Workplace Client for Windows - Issue 1.0**

## **Abstract**

These Application Notes describe the configuration steps required to integrate EPOS Connect, EPOS BTD 800 Dongle and EPOS ADAPT 200 Series Bluetooth Headset with Avaya Workplace Client for Windows.

Readers should pay attention to **Section 2**, in particular the scope of testing as outlined in **Section 2.1** as well as any observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

# 1. Introduction

The EPOS ADAPT 200 Series Bluetooth Headset connects to the PC via Bluetooth (BT) using EPOS BTD 800 Dongle. Together with EPOS Connect software, it allows connection and call control of Avaya Workplace Client for Windows (hereafter referred to as Avaya Workplace). The EPOS Connect is a collection of programs that enable remote call control with EPOS headsets and Avaya Workplace for Windows. Users can directly answer, end, mute/unmute and adjust volume with the headset.

The following EPOS ADAPT 200 Series headsets were used for compliance testing.

- ADAPT 261

**Note:** See the EPOS Declaration of Compliance, **Attachment 1**, which provides details of other EPOS ADAPT 200 Series headsets models for which this testing applies. For additional information contact EPOS support as shown in **Section 2.3**.

## 2. General Test Approach and Test Results

The interoperability compliance test included feature and serviceability testing. The feature testing focused on placing calls with Avaya Workplace, answering and ending calls using the call control button on the EPOS headset, and verifying two-way audio. The call types include calls to voicemail, local extensions, and the PSTN. Auto-answer, call hold and resume, mute and un-mute, and volume were also tested.

The serviceability testing focused on verifying the usability of the EPOS headset solution after restarting the Avaya Workplace, restarting the PC, reconnecting the headset USB cable to the PC and moving away from the BT range.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

Avaya recommends our customers implement Avaya solutions using appropriate security and encryption capabilities enabled by our products. The testing referenced in these DevConnect Application Notes included the enablement of supported encryption capabilities in the Avaya products. Readers should consult the appropriate Avaya product documentation for further information regarding security and encryption capabilities supported by those Avaya products.

Support for these security and encryption capabilities in any non-Avaya solution component is the responsibility of each individual vendor. Readers should consult the appropriate vendor-supplied product documentation for more information regarding those products.

For the testing associated with these Application Notes, the interface between Avaya systems and endpoints utilized enabled capabilities of TLS/SRTP.

Avaya's formal testing and Declaration of Conformity is provided only on the headsets/handsets that carry the Avaya brand or logo. Avaya may conduct testing of non-Avaya headset/handset to determine interoperability with Avaya phones. However, Avaya does not conduct the testing of non-Avaya headsets/handsets for: Acoustic Pressure, Safety, Hearing Aid Compliance, EMC regulations, or any other tests to ensure conformity with safety, audio quality, long-term reliability or any regulation requirements. As a result, Avaya makes no representations whether a particular non-Avaya headset will work with Avaya's telephones or with a different generation of the same Avaya telephone.

Since there is no industry standard for handset interfaces, different manufacturers utilize different handset/headset interfaces with their telephones. Therefore, any claim made by a headset vendor that its product is compatible with Avaya telephones does not equate to a guarantee that the headset will provide adequate safety protection or audio quality.

## **2.1. Interoperability Compliance Testing**

All test cases were performed manually. The following features were verified:

- Placing calls to the voicemail system. Voice messages were recorded and played back to verify that the playback volume and recording level were good.
- Placing calls to internal extensions to verify two-way audio.
- Placing calls to the PSTN to verify two-way audio.
- Answering and ending calls using the call control button on the headset and the soft button on Avaya Workplace.
- Using the soft button on Avaya Workplace to hold and resume the audio.
- Using the volume buttons on the headset to adjust the audio volume.
- Using the mute button on the headset and the soft button on Avaya Workplace to mute and un-mute the audio and verifying the mute status.
- Verifying incoming call notification.
- Verifying call ended notification.

For the serviceability testing, reconnect the BT dongle, power cycle the headset, restart Avaya Workplace and moving out of the BT range are tested to verify proper operation of the headset.

## **2.2. Test Results**

All test cases were completed successfully.

## 2.3. Support


For support on this EPOS headset solution, contact EPOS Technical Support below where sign-in is required:

- Website: <https://eposaudio.com/support/>

## 3. Reference Configuration

**Figure 1** illustrates the test configuration used to verify the EPOS Connect and EPOS ADAPT 200 Series headset with Avaya Workplace. The EPOS Connect software was installed on the PC together with Avaya Workplace. The EPOS headsets were connected via BT dongle into the PC USB interface. The following EPOS ADAPT 200 Series BT headsets were tested:

- ADAPT 261



**Figure 1: Test Configuration**

## 4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided.

Equipment/Software	Release/Version
Avaya Aura® Communication Manager	10.1.0 (10.1.0.0.0.974.27247)
Avaya G430 Media Gateway	42.4.0
Avaya Aura® System Manager	System Manager 10.1.0.0 Build No. - 10.1.0.0.537353 Software Update Revision No: 10.1.0.0.0614119
Avaya Aura® Session Manager	10.1.0 (10.1.0.0.1010019)
Avaya Aura® Media Server	8.0.2.218
Avaya Messaging	10.8 SP1SU2
Avaya 96x1 Series H.323 Deskphones	6.8511
Avaya J100 Series SIP Deskphones	4.0.11.0
Avaya Workplace Client running on Windows 10 Pro	3.25
EPOS ADAPT 200 Series Headsets <ul style="list-style-type: none"><li>ADAPT 261</li></ul>	1.5.2
EPOS BTD 800 Dongle	2.17.16
EPOS Connect for Windows	7.1.0.24484

## 5. Configure Avaya Aura® Communication Manager

It is implied a working Communication Manager system is already in place, including dial plans and SIP trunks to a Session Manager. For all other provisioning information such as initial installation and configuration, please refer to the product documentation in **Section 11**.


## 6. Configure Avaya Aura® Session Manager

This section describes aspects of the Session Manager configuration required for Avaya Workplace to register. It is assumed that the Domains, Locations, SIP entities, Entity Links, Routing Policies, Dial Patterns and Application Sequences have been configured where appropriate for Communication Manager, Session Manager and Messaging.

Session Manager is managed via System Manager. Using a web browser, access **https://<ip-addr of System Manager>/SMGR**. In the **Log On** screen, enter appropriate **User ID** and **Password** and click the **Log On** button.

## 6.1. Verify Session Manager Ports for SIP endpoint registration

Each Session Manager Entity must be configured so that the SIP Endpoint can register to it. From the home page, under **Elements**, click **Routing** → **SIP Entities** (not shown) and select the Session Manager entity used for registration. Make sure that **TCP**, **UDP** and **TLS** entries are present under **Listen Ports**. During the compliance test, Avaya Workplace registered to the Session Manager using TLS transport.

Listen Ports					
Add Remove					
3 Items  Filter: Enable					
<input type="checkbox"/>	Listen Ports	Protocol	Default Domain	Endpoint	Notes
<input type="checkbox"/>	5060	TCP	sglab.com	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	5060	UDP	sglab.com	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	5061	TLS	sglab.com	<input checked="" type="checkbox"/>	

Select : All, None


## 6.2. Add SIP User

The addition of SIP User will not be detailed here. Refer to details in adding user in the administration document for Avaya Aura® Session Manager in [4].




## 7. Configure Avaya Workplace


Avaya Workplace is a SIP soft phone application that provides users with access to Unified Communications (UC) services. This section shows how to configure the EPOS ADAPT 200 Series to use with Avaya Workplace.

From Avaya Workplace, navigate to **Settings** → **User Preferences** → **Audio/Video**.





Select *EPOS BTD 800* for Microphone  and the same for Speakers  as shown below assuming ADAPT 261 is used for headset. It is optional for Ringing on incoming calls  to be set as *EPOS BTD 800*.



## 8. Configure EPOS ADAPT 200 Series Headset solutions

This section covers the steps to integrate EPOS ADAPT 200 Series headset with Avaya Workplace, including:

- Installing the EPOS Connect Software
- Connect the EPOS headset
- Configuring EPOS headset with EPOS Connect

**Note:** After successfully performing this procedure, the EPOS headset will be detected in Avaya Workplace as described in **Section 7**.


### 8.1. Installing the EPOS Connect Software

EPOS Connect software can be obtained from EPOS support portal at <https://eposaudio.com/support/>. Installation of the software is done through executing the .exe file and following the prompt.

### 8.2. Connect the EPOS headset

Plug the EPOS ADAPT 200 Series headset cable into the USB port of the PC. The device drivers will automatically be installed. Refer to the EPOS ADAPT 200 document in **Section 10** for pairing of BTD 800 Dongle with the ADAPT 200 Series Headset.

Open the EPOS Connect program installed on the PC. Select the **Home** icon and check that the headset is detected as shown below which is for one of the headsets ADAPT 261.



### 8.3. Configuring EPOS headset with EPOS Connect

Open the Avaya Workplace program and click the EPOS Connect program **Settings** at the bottom (not shown). Verify the **Default Headset** is properly detected. Check that the **Default Softphone** is set as **Avaya Workplace**. Otherwise, click the drop-down menu of **Default Softphone** to select. Click **Save Settings** at the bottom right to retain it.


Feature	Setting
<b>Headset</b>	
Default Headset	BTD 800
<b>Softphone</b>	
Default Softphone	Avaya Workplace
<b>General</b>	
Pause Media	<input checked="" type="checkbox"/>

[Restore Settings](#) [Save Settings](#)

## 9. Verification Steps

This section verifies that the EPOS solution has been successfully integrated with Avaya Workplace.

1. Open the EPOS Connect program to verify that the headset has been successfully connected to PC for use with Avaya Workplace running. Observed that EPOS ADAPT 200 Series headset is detected as detailed in **Section 8.2**.
2. Make incoming and outgoing calls and verify that calls can be established with two-way audio. For incoming calls, answer the call by pressing the call control button on the headset (as shown below).



3. End the call by pressing the same call control button on the headset.
4. Verify also that the headset is able to remotely control call functions such as mute/unmute and adjust the volume. Similarly, verify such call control functions could be done on the Avaya Workplace.



## 10. Conclusion

These Application Notes describe the configuration steps required to integrate EPOS Connect, EPOS BTD 800 Dongle and EPOS ADAPT 200 Series Bluetooth Headset with Avaya Workplace Client for Windows. All test cases were completed successfully.

## 11. Additional References

This section references the Avaya and EPOS documentation that are relevant to these Application Notes.

The following Avaya product documentation can be found at <http://support.avaya.com>.

- [1] *Administering Avaya Aura® Communication Manager*, Release 10.1, Issue 1, Dec 2021.
- [2] *Planning for and Administering Avaya Workplace Client for Android, iOS, Mac and Windows*, May 31, 2021.
- [3] *Using Avaya Workplace Client for Android, iOS, Mac, and Windows*, May 31, 2021.
- [4] *Administering Avaya Aura® Session Manager*, Release 10.1, Issue 1, Dec 2021.

The following EPOS documentation can be found at <http://www.eposaudio.com>.

- [5] *EPOS ADAPT 231/ADAPT 261 User Guide*.

---

**©2022 Avaya Inc. All Rights Reserved.**

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at [devconnect@avaya.com](mailto:devconnect@avaya.com).

EPOS Group A/S

Industriparken 27,  
DK-2750 Ballerup, Denmark

eposaudio.com

## Declaration of Compliance

We, EPOS Group A/S, declare under sole responsibility that within EPOS ADAPT 200 series there are more variants that have similar features, differences affecting only the wearing style and connectivity.


These differences have no other impact on firmware (FW) functionality. The schematics of RF board is 100% the same. The firmware version is also the same. The attached headsets which define the acoustics are 100% the same.

		USB & Smartphone / Tablet connectivity
Product sales name		ADAPT 260 USB-A / ADAPT 261 USB-C On-ear, double-sided USB-A / USB-C headset ADAPT 230 USB-A / ADAPT 231 USB-C On-ear, single-sided USB-A / USB-C headset
Product similarities		Firmware version RF PCBA Schematic Acoustical design
Differences	Wearing style	Single vs Double sided headset
	Connectivity	USB-A / USB-C
connection method to Avaya Workplace		USB-A / USB-C direct



Theis Mørk (Mar 14, 2022 10:05 GMT+1)

**Theis Mørk**  
Vice President, Product Management  
& Strategic Alliances  
EPOS A/S



Petru Faurescu (Mar 14, 2022 11:33 GMT+1)

**Petru Faurescu**  
Global Strategic Alliance Manager  
EPOS A/S

*EPOS Group A/S*

Industriparken 27,

DK-2750 Ballerup, Denmark

[eposaudio.com](http://eposaudio.com)

## Appendix 1. Images displaying the differences

### **ADAPT 260 USB-A / ADAPT 261 USB-C**



### **ADAPT 230 USB-A / ADAPT 231 USB-C**

