

## Avaya Solution & Interoperability Test Lab

# **Application Notes for Algo 8128 SIP Strobe Light with Avaya IP Office - Issue 1.1**

#### **Abstract**

These Application Notes describe the configuration steps required for Algo 8128 SIP LED Strobe to interoperate with Avaya IP Office. The Algo 8128 SIP Strobe Light is a SIP compliant Power over Ethernet high intensity strobe light for alerting and notification of telephone, emergency, safety, and security events.

Readers should pay attention to section 2, in particular the scope of testing as outlined in **Section 2.1** as well as the observations noted in **Section 2.2**, to ensure that their own use cases are adequately covered by this scope and results.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

## 1. Introduction

These Application Notes describe the configuration steps required for Algo 8128 SIP Strobe Light to interoperate with Avaya IP Office. Algo 8128 SIP Strobe Light is a SIP-based device that can register with Avaya IP Office as SIP endpoint.

The 8128 SIP Strobe Light is a SIP compliant Power over Ethernet (PoE) high intensity strobe light for alerting and notification of telephone, emergency, safety, and security events.

## 2. General Test Approach and Test Results

The feature test cases were performed manually. The focus of this interoperability compliance testing was to verify if Algo 8128 can register as a SIP endpoint on IP Office and to verify proper operation of the Algo 8128 SIP Strobe when integrated with Avaya IP Office.

DevConnect Compliance Testing is conducted jointly by Avaya and DevConnect members. The jointly-defined test plan focuses on exercising APIs and/or standards-based interfaces pertinent to the interoperability of the tested products and their functionalities. DevConnect Compliance Testing is not intended to substitute full product performance or feature testing performed by DevConnect members, nor is it to be construed as an endorsement by Avaya of the suitability or completeness of a DevConnect member's solution.

## 2.1. Interoperability Compliance Testing

Compliance testing verified that the 8128 was able to interoperate with the telephones residing on IP Office system. The following interoperability areas were covered:

- The 8128 can register to IP Office as a SIP endpoint.
- SIP Ring The 8128 will flash/alert when the twinning extension is called.
- SIP Monitor The 8128 can monitor a telephone on IP Office when this telephone is called the 8128 will flash/alert.

The serviceability testing focused on verifying the ability of Algo 8128 SIP Strobe Light to recover from adverse conditions, such as disconnecting/reconnecting the Ethernet cable to the device.

#### 2.2. Test Results

The objectives outlined in **Section 2.1** were verified. All test cases passed.


## 2.3. Support

Technical support on Algo 8128 SIP Strobe Light can be obtained through the following:

- Phone: + 1 604 454 3792
- Web: http://www.algosolutions.com/support/support.html
- Email: support@algosolutions.com

## 3. Reference Configuration

**Figure 1** illustrates the test configuration used during the compliance testing between the Avaya IP Office and Algo 8128 SIP Strobe Light. The 8128 SIP Strobe Light communicated with IP Office through Avaya switch with Power over Ethernet (PoE) and registered with Avaya IP Office as SIP endpoint. The PRI T1 trunk was also configured to connect from IP Office to PSTN for test cases off-net via PRI T1 trunk.



**Figure 1: Test Configuration Diagram** 

## 4. Equipment and Software Validated

The following equipment and software were used for the sample configuration provided:

Equipment	Software
Avaya IP Office 500V2	9.0.3.941
Avaya H.323 9620L IP Deskphone	3.220A
Avaya H.323 9650C IP Deskphone	3.220A
Avaya 1140E SIP Phone	4.3
Avaya 9508 Digital Phone	0.55
Algo 8128 SIP Strobe Light	2.3

## 5. Configure Avaya IP Office


This section provides the procedures for configuring Avaya IP Office. The procedures include the following areas:

- Verify IP Office license.
- Obtain LAN IP address.
- Administer SIP registrar.
- Administer SIP extensions.
- Administer SIP users.
- Administer Internal Twinning.

## 5.1. Verify IP Office License


From a PC running the Avaya IP Office Manager application, select **Start**  $\rightarrow$  **Programs**  $\rightarrow$  **IP Office**  $\rightarrow$  **Manager** to launch the Manager application. Select the proper IP Office system, and log in using the appropriate credentials.

The **Avaya IP Office Manager** screen is displayed. From the configuration tree in the left pane, select **License**, the list of license displayed in the right panel. Verify that the **3rd Party IP Endpoints** status is "**Valid**".




#### 5.2. Obtain LAN IP Address

From the configuration tree in the left pane, select **System** to display the DevCon IPO 1 screen in the right pane. Select the **LAN1** tab, followed by the **LAN Settings** sub-tab in the right pane. Make a note of the **IP Address**, which will be used later to configure Algo 8128. Note that IP Office can support SIP extensions on the **LAN1** and/or **LAN2** interfaces, and the compliance testing used the **LAN1** interface.




## 5.3. Administer SIP Registrar

Continuing from **Section 5.2**, select the **VoIP** sub-tab. Make certain that **SIP Registrar Enable** is checked, as shown below. Enter a valid **Domain Name** for SIP endpoints to use for registration with IP Office. In the compliance testing, the **Domain Name** was left blank, so the SIP endpoints used the LAN IP address for registration.




#### 5.4. Administer SIP Extensions

From the configuration tree in the left pane, right-click on **Extension**, and select **New**  $\rightarrow$  **SIP Extension** (not shown) from the pop-up list to add a new SIP extension. For **Base Extension**, enter the SIP strobe light extension "28257". Retain the default values in the remaining fields.




Select the **VoIP** tab, and retain the default values in all fields. Repeat this section to add additional SIP extensions as desired.




#### 5.5. Administer SIP User

From the configuration tree in the left pane; right-click on **User tab** and select **New** (not shown) from the pop-up list. Enter desired values for **Name**. For **Extension**, enter the Algo extension from **Section 5.4**. Remember these values as they will be needed to register Algo to IP Office. Enter desired values for **Password**, this password is used when user want to login IP Office Softphone.




Select the **Telephony** tab, followed by the **Supervisor Settings** sub-tab, and enter a desired **Login Code**. This **Login Code** is needed to register Algo 8128 to IP Office.




## 5.6. Administer Internal Twinning

From the configuration tree in the left pane, select the desk phone user that will be associated with the SIP strobe user. In this case, desk phone user "Extn28232".



Select the **Mobility** tab, and check **Internal Twinning**. For the Twinned Handset, select the strobe extension user from Section 5.5. Retain the default values in the remaining fields. Note that with the Internal Twinning configuration, the Algo extension 28257 will be acting like a secondary extension of the extension 28232 which is configured as primary and a direct call to the secondary will always get busy. This is the design intent of the Internal Twining feature in IP Office. In order to place a direct call to the Algo strobe light extension, do not configure it twinned with a deskphone.




## 6. Configure Algo 8128 SIP Strobe Light

This section provides the procedures for configuring Algo 8128 SIP Strobe Light. The procedures include the following areas:

- Launch web interface
- Administer configuration

#### 6.1. Launch Web Interface


Access the 8128 SIP Strobe Light web-based interface by using the URL "http://ip-address" in an Internet browser window, where "ip-address" is the IP address of the Algo 8128 SIP Strobe Light. This IP address can obtain from the Algo locator tool. The **Welcome to the Algo 8128 SIP LED Strobe Control Panel** screen is displayed, as shown below. Log in using the appropriate credentials.




## 6.2. Administer Algo 8128

Select **Basic Settings**  $\rightarrow$  **SIP** from the top menu, to display the screen below. Configure the **SIP Settings** section toward the bottom of the screen as desired to match the configuration. Enter the following values for the specified fields, and retain the default values in the remaining fields.

- **SIP Domain (Proxy Server):** The LAN IP address from **Section 5.2**.
- Extension: The SIP base extension from Section 5.4.
- **Authentication ID:** The SIP user name from **Section 5.5**.
- Authentication password: The SIP user login code from Section 5.5.
- Monitor Mode: There are three options for this field and during the certificate test the Monitor and Use "Subscribe/Notify" modes were verified.
  - Select Monitor "Ring" event of the SIP registered extension option. When this
    mode is used the 8128 will flash when called directly, or if the 8128 is twinned
    with another extension, it will also flash when the twinned extension is called.



- Select Use "Subscribr/Notify" dialog event option this will extend two sub fields below. This mode on the 8128 was used to monitor an extension on IPO.
  - Monitor Extension: Enter an extension on IPO that the 8128 will monitor.
  - Monitor Call Events: Select an event that triggers the monitor from the 8128.




## 7. Verification Steps

This section provides the tests that can be performed to verify proper configuration of Avaya IP Office and Algo 8128 SIP Strobe Light.

## 7.1. Verify Avaya IP Office

From a PC running the Avaya IP Office Monitor application, select **Start** → **Programs**→ **IP Office** → **System Monitor** to launch the application. The **Avaya IP Office SysMonitor** screen is displayed, as shown below. Select **Status** → **SIP Phone Status** from the top menu.




The **SIPPhoneStatus** screen is displayed. Verify that there is an entry for each SIP extension from **Section 5.4**, that the **User Agent** is "Algo-8128", and that the **Status** is "SIP: Registered", as shown below.



## 7.2. Verify Algo 8128 SIP Strobe Light

From the Algo 8128 SIP Strobe Light web-based interface, select **Status** from the top menu. Verify that **SIP Registration** displays "Successful" in the **SIP Registration** as shown below.



The following tests were conducted to verify the solution between the Algo 8128 and Avaya IPO.

- Verify that the 8128 flashes when placing a call to the 8128 Strobe and it stops flashing when the caller hangs up the call.
- Verify that the 8128 flashes in the event of Ring or In-Use of monitored extension on IPO and it stop flashing when the event ends.

#### 8. Conclusion

All of the executed test cases have passed and met the objectives outlined in **Section 2.1**, with some exceptions outlined in **Section 2.2**. Algo 8128 SIP Strobe Light version 2.3 is considered to be in compliance with Avaya IP Office System Release 9.0.

#### 9. Additional References

Product documentation for the Avaya IP Office may be found at: <a href="https://support.avaya.com/css/Products/">https://support.avaya.com/css/Products/</a>

Product documentation for the Algo 8128 SIP Strobe Light products may be found at: <a href="http://www.algosolutions.com/products/Audible-and-Visual-Alerting/8128-sip-strobe-light.html">http://www.algosolutions.com/products/Audible-and-Visual-Alerting/8128-sip-strobe-light.html</a>

Avaya IP Office Documents:

- [1] IP Office 9.0 Installation, Document number 15-601042 Issue 28, 11 October 2013
- [2] IP Office 9.0 Manager 9.0, Document number 15-601011 Issue 9.01, 09 September 2013 IP Office 9.0 Administering Voicemail Pro, Document number 15-601063 Issue 9.0 Release 1.0, September 2013

#### ©2015 Avaya Inc. All Rights Reserved.

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and TM are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data, and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at devconnect@avaya.com.